

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10662

Date In:	17 JUN 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	10828
:	:	Year:	2023
Customer Name:	17017 - BRUESEWITZ, SC	Manufacturer:	FOREST RIVER
Address:	3320 ALDER ST	Brand:	FLAGSTAFF SUPER-LITE T
:	STEVENS POINT, WI	Model:	26RBWS
Postal/Zip:	54481	Miles/Hrs:	0
Phone#(res):	7152526000	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	SBRUESEWITZ35@YAHOO.CO	Tag#:	CMR PU 6/22
Purchased Date:	23 AUG 23	:	:
Delivery Date:	05 SEP 23	:	:
InService Date:	:	:	:
Serial#:	4X4TFLB21PZ187504	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  CUSTOMER STATES THAT THE WATER PUMP IS      W      1021  FORES
                INOP- CUSTOMER STATES THAT WHEN YOU TRY
                TO RUN THE PUMP THERE IS NO NOISE, NO
                HUM- ALMOST AS IF THERE IS NO POWER-
                CUSTOMER STATES THAT THE DAY PRIOR IT
                WAS OPERATING PERFECTLY- WOULD LIKE TO
                HAVE DIAGNOSED-
      CAUSE:      I plugged in the camped and turned on
                the water pump button. Nothing happened.
                So I located the water pump, checked
                voltage at the connections, and in the
                process, the pump turned on. I think the
                connector was loose on the water pump
                (not punched all the way in). Hard to
                say. Was not able to replicate the issue
                again.
      CORRECTION:  .  LOOSE CONNECTION
2      COMPLAINT:  CUSTOMER STATES THAT WE HAD FIXED THE      W      1021  FORES
                TRACK/RAIL FOR THE BEDROOM BARN DOOR ON
                PREVIOUS RO. NOW THE DOOR KEEPS POPPING
                OF THE TRACK.
      CAUSE:      One of the hardware pieces on top of the
                sliding door was broken, allowing the
                door to fall.  Need to replace.
      CORRECTION:  Had to remove the trim piece above the
                sliding door to access the door
                hardware. Then I removed the broken
                bracket and replaced with a new bracket.
```

Continued on page 2

Work Order : 10662

Job #	Description	JOB INFORMATION	Type Bill To
-------	-------------	-----------------	--------------

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
2	756815205559	SLIDING DOOR HANGER		W-1021	1	4.17	4.17

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
1	WARR	MANUFACTURER WARRANTY	NOK		W-1021	0.50	115.00	57.50
2	WARR	MANUFACTURER WARRANTY	NOK		W-1021	0.50	115.00	57.50

BILLINGS SUMMARY							
Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total	
W 1021	4.17	115.00	0.00	0.00	0.00	119.17	
Totals	4.17	115.00	0.00	0.00	0.00	119.17	

&k2S

&k0S