

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10678

Date In:	20 JUN 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	
:		Year:	2023
Customer Name:	17383 - GAMLIN, ERIK	Manufacturer:	FOREST RIVER
Address:	1348 GLACIER DR	Brand:	WILDWOOD
:	BYRON, IL	Model:	42FK
Postal/Zip:	61010	Miles/Hrs:	
Phone#(res):	8159044825	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	4X4TWD829PM062275	:	

Job #	Description	JOB INFORMATION	Type	Bill To
1	MOBILE SERVICE CALL TO OASIS CAMPGROUND SITE #79 ***THERE IS A KEY TO THE UNIT IN A MAGNETIC KEY BOX BY THE WATER HEATER*** **SERVICE CALL IS TO BE BILLED TO GENERAL RV- ATTENTION JASON- GENERAL RV (847)669-5570		E	17383 GAMLI
2	COMPLAINT: CUSTOMER STATES THAT THE KITCHEN TABLE IS STARTING TO BUBBLE UP- CAUSE: pics and measurements taken of kitchen table the paint peeled and bubbles will need a new table CORRECTION: Will need a new kitchen table REQUEST PART NUMBER: F100445369 REQUEST 1 HOUR OF LABOR		W	1021 FORES
3	COMPLAINT: CUSTOMER STATES THAT THE EMERGENCY EXIT HANDLE IS BROKEN OFF- IT IS THE WINDOW THAT IS ABOVE THE KITCHEN TABLE- CAUSE: pics taken the handle is broken and is replaceable CORRECTION: Will need a new will latch REQUEST: .50 LABOR PART		W	1021 FORES
4	COMPLAINT: CUSTOMER REQUESTS HAVING THE KITCHEN BLIND DOES NOT GO ALL THE WAY DOWN- IT IS THE BLIND THAT IS RIGHT NEXT TO THE FRIDGE- CAUSE: pics taken and the shade has holes in it and doesn't pull all the way down CORRECTION: Will need a new shade for kitchen to the the of refrigerator REQUEST: .50 LABOR		W	1021 FORES

Continued on page 2

Work Order : 10678

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
PART
5      COMPLAINT:  CUSTOMER STATES THAT THE BATTERY COVER    W    1021    FORES
           IS MISSING-
           CAUSE:    pics and measurements taken they have
           the wrong size battery box cover
           CORRECTION: Will need the correct battery box
           cover... REQUEST: .20 LABOR PART
6      COMPLAINT:  CUSTOMER STATES THAT THE PANTRY DOOR      W    1021    FORES
           CAUGHT ON THE SLIDE AND BROKE THE PANTRY
           DOOR (THE HANDLE BENT INTO THE WOOD)
           CAUSE:    pics and measurements taken of door and
           handle will need a new door handle
           assembly I did take pics of door just in
           case the door is a little scuffed up
           around door handle so that's your call
           CORRECTION: needs door handle assembly ... REQUEST:
           1 HOUR LABOR PARTS: DOOR: F100127808
           NEED DOOR HANDLE

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
2 WARR  MANUFACTURER WARRANTY JS W-1021  0.10  115.00  11.50
3 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  115.00  57.50
4 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  115.00  57.50
5 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  115.00  57.50
6 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  115.00  57.50

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
1 SSE  SHOP SUPPLIES - EXTERNAL E-17383  1.00  0.00  0.00
1 SC  SERVICE CALL E-17383  0.00  3.75  0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1021  0.00  241.50  0.00  0.00  0.00  241.50
Totals  0.00  241.50  0.00  0.00  0.00  241.50

```

&k2S
&k0S