

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10755C

Date In:	27 JAN 25	Author:	MZYWICKI
Promised Date:	31 MAY 25	Stock No:	11106
:	:	Year:	2024
Customer Name:	17376 - IPANIS, DEBORA	Manufacturer:	FOREST RIVER
Address:	6119 LOGAN AVENUE SOUT	Brand:	PUMA TT
:	MINNEAPOLIS, MN	Model:	30RKQS
Postal/Zip:	55419	Miles/Hrs:	0
Phone#(res):	6127190828	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	14 JUN 24	:	:
Delivery Date:	18 JUL 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUF20RP101546	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT: CUSTOMER STATES THAT THE ENTRY DOOR AND FRAME WILL NOT SHUT RIGHT. CAUSE: Entrance door adjustment. CORRECTION: Adjusted the camber in door for better closure. REQUEST .40 FOR LABOR		W	1021 FORES
2	COMPLAINT: CUSTOMER STATES THERE IS A WATER LEAK UNDER THE KITCHEN SINK (NEAR THE BACK WALL) CAUSE: Water leak at the outside spray port. CORRECTION: Tighten loose water line fitting to spray port. Then tested for leaks with antifreeze. No leaks. REQUESTING .40 FOR LABOR		W	1021 FORES
3	COMPLAINT: CUSTOMER STATES THAT THERE ARE SOME KITCHEN CABINETS THAT LOOK WARPED- NEED TO BE INSPECTED FOR WARRANTY- CAUSE: Cabinet doors in kitchen are in need of adjustment. CORRECTION: Adjusted hinges on cabinet doors for more even closure. REQUESTING .20 FOR LABOR		W	1021 FORES
4	COMPLAINT: CUSTOMER STATES THAT THE BACK OF THE RECLINER NEXT TO THE BOOTH IS BROKEN- CAUSE: Back rest of recliner on left has loose mounting brackets. CORRECTION: Tighten brackets on back rest. REQUESTING .20 FOR LABOR		W	1021 FORES
5	COMPLAINT: CUSTOMER STATES THAT THERE IS A TEAR ON		W	1021 FORES

Continued on page 2

Work Order : 10755C

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        THE RECLINER CORNER IN THE UPPER BACK-
CAUSE:  Back of recliner near the top is torn
        from catching the bottom of window from
        which also bent the window frame. Will
        need a new backrest. Pics of tags on
        backrest line.
CORRECTION: REQUEST 1 HOUR OF LABOR AND NEW BACKREST
6 COMPLAINT: CUSTOMER STATES THAT THE WINDOW FRAME   W   1021   FORES
        BEHIND THE THE RECLINER IS BENT-
CAUSE:  Window ring is bent behind recliners.
        48"x21-3/4". Need to order.
CORRECTION: REQUESTING 1 HOUR LABOR AND NEW FRAME
7 COMPLAINT: CUSTOMER STATES THAT THE BEDROOM DOOR IS W   1021   FORES
        WARPED AND DOES NOT LINE UP-
CAUSE:  Bedroom door adjustment. Not even in
        opening.
CORRECTION: Adjusted the hinges from top to bottom
        to get door to sit more even all the way
        around the opening. REQUESTING 1 HOUR
        LABOR
    
```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  1  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
  2  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
  3  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
  4  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
  5  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.47  115.00  54.05
  5  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.03  115.00   3.45
  6  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
  7  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.00  115.00   0.00
  7  WARR      MANUFACTURER WARRANTY  TD  W-1021  0.50  115.00  57.50
    
```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1021            0.00  402.50   0.00   0.00   0.00  402.50
      Totals      0.00  402.50   0.00   0.00   0.00  402.50
    
```

&k2S
&k0S