

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2051032  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TFLX23RD457986  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010B  
 ITEM # FLT22FBS  
 DEALER RO # 10779B  
 CLAIM START DATE 09/09/2024  
 CLAIM END DATE 10/04/2024

Labor rate: \$115.00

**OWNER INFORMATION**

HOWARD SCHUSTER  
 505 HONEYDALE RD #56  
 Brownsville, TX 78520  
 USA

Retail Date of Purchase 09/05/2024

WARRANTY EXPIRATION DATE 09/05/2025

**Claim Line Details**

**Labor**

Line# 1	Operation Code SB-387-09-00-004564	Operational Description 51-1798 - MAGIC CHEF REFRIGERATOR VENTS NOT CUT OUT - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Refrigerator/Perform/No Tread Code
---------	---------------------------------------	--

**Complaint, Cause, Correction**

Original Note : greeneway@dealer-advisors.com, 2024-09-09 09:55:37 :: Complaint: MFG Recall 51-1798 The magic chef refrigerator may not have the proper bents cut out inside the refrigerator, potentially causing cooling issues. Cause: Recall 51-1798, recall needed. Correction: Vents cut for recall

Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$40.25
Serial#	Appr Hrs	0.35	Appr Labor Amt	\$40.25

**Notes**

note - We are authorizing the 0.35 hours for this repair with the understanding that the updated version of the TSB, released on Dealer Connect on August 8, 2024, has been correctly performed. Please ensure all aspects of the update are completed according to the latest guidelines/version of this TSB. Thank you!

<b>Submitted</b>	Labor Amt	\$40.25
	Parts & Freight	\$0.00
	Total	\$40.25

<b>Approved</b>	Labor Amt	\$40.25
	Parts & Freight	\$0.00
	Total	\$40.25

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 All repairs described have been inspected and are satisfactory.