

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10842

Date In:	19 JUL 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11201
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	429LFT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	27 JUL 24	:	:
Delivery Date:	14 SEP 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPU820SP103171	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NTTS    COMPLAINT:  NEW TRAVEL TRAILER STOCK /sold PREP          I      PDI      PRE-D
        CAUSE:      New TT, sold stock prep, should have
        CORRECTION: Inspected and tested new sold unit for
        buyer.
CEN     COMPLAINT:  CLEAN EXTERIOR- NEW                          I      PDI      PRE-D
        CAUSE:      DIRTY
        CORRECTION: CLEAN
ISRO    COMPLAINT:  INTERNAL STOCK REPAIR 01 - Drawer           W      1021     FORES
        CAUSE:      Slide crushed drawer, found when
        starting prep. Will need 1.7 to rebuild
        the drawer, lots of details and time to
        take apart, cut new boards, fix
        guides,and put back together. not an
        average drawer build had to make sure it
        would not get crushed again so it took a
        few times and making different cuts, etc
        to get it to work correctly.
        CORRECTION: Rebuilt drawer, disassembled and cut new
        sides. Routered indents for base.
        Reassembled. Replaced slide hardware.
        Works ok.
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Gas Leak, Manometer    W      1021     FORES
        CAUSE:      Manometer test dropped 1.5psi over 3
        minutes and 2psi over 5 minutes. Very
        slow gas leak. Found very small bubbles
```

Continued on page 2

Work Order : 10842

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                with soap test at furnace fitting. will
                                need 1 hr for all testing and diagnosing
                                and repairing.
CORRECTION: Tightened furnace fitting and retested
gas leak with nanometer. Tested ok. No
more leaking.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - wall panel seam in    W    1021    FORES
                                bedroom coming apart
CAUSE:    Defective construction 1.5h to repair.
Order 1" seam tape.
CORRECTION: Pull 4'length of seam tape off, clean
residue from tape.      Reattach wall
panels pulling off frame. Pound in
staples, add a couple more. Reapply seam
tape.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Black markings all    W    1021    FORES
                                over kitchen floor area.
CAUSE:    black marks on lino, cannot say what
caused it needed .50 to get it all
cleaned up
CORRECTION: cleaned with rag and cleaner.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Bunk wall bracket    W    1021    FORES
                                loose
CAUSE:    Screws pulled loose for bunk bracket
Will need .20 for repair.
CORRECTION: Used slightly longer screws to hold
bracket in place. Screws were only 1"
protrusion into the wall
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Trim in bunkhouse    W    1021    FORES
                                laying on floor
CAUSE:    Nails were too far in, nothing to hold
trim in place Will need .30 for repair.
CORRECTION: Pin nailed to secure
1        COMPLAINT:  THE FURNACE IS NOT OPERATING CORRECTLY- W    1021    FORES
CAUSE:    Furnace not receiving full power from
power source. Voltage meter showing
10.4v    Furnace only working
intermittently.    Tested using a 12.7v
battery, furnace working fine on
dedicated power source.    New power
lead needs to be run from distributor
box in rear bathroom, to front bedroom
where furnace is located. Around 40'
A considerable undertaking involving
dropping underbelly.    (4 hours to fix)
Drop underbelly, feed new power wire,
test, rescue underbelly.
CORRECTION: Dropped sections of the underbelly.
Fished a new double insulated 12g wire

```

Continued on page 3

Work Order : 10842

from box to furnace. Wired up furnace
side. Wired up Distro side. Tested
furnace, working fine now, full voltage.
Resecured underbelly. Closed
distribution box.

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
NTTS  146508        BATTERY BOX GROUP 24      I-PDI        0        8.84        0.00
NTTS  840821034507  12V 24 MDP BATTERY      I-PDI        0       85.20        0.00
CEN   014717396042  HTS STANDARD 10' SEWER H I-PDI        1        7.46        7.46
CEN   019079236326  TOILET TISSUE, SGL. 2 PL I-PDI        1        1.02        1.02
CEN   019079900142  PARK ADAPTER BULK 30-15  I-PDI        1        3.34        3.34
CEN   093344312410  ADAPTER 30 AMP MALE TO 5 I-PDI        1       24.55       24.55
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
NTTS  RV1F-1A    NEW STOCK PREP      RW      I-PDI        1.37     70.00     95.90
NTTS  RV1F-1A    NEW STOCK PREP      RW      I-PDI        0.17     70.00     11.90
NTTS  RV1F-1A    NEW STOCK PREP      RW      I-PDI        1.41     70.00     98.70
NTTS  RV1F-1A    NEW STOCK PREP      RW      I-PDI        0.61     70.00     42.70
NTTS  RV1F-1A    NEW STOCK PREP      RW      I-PDI        0.94     70.00     65.80
NTTS  RV1F-1A    NEW STOCK PREP      I-PDI        0.00     70.00        0.00
CEN   CE        CLEAN EXTERIOR      EJ      I-PDI        3.73     70.00    261.10
ISR01 Z991      MISC LABOUR CODE (INTE RW      W-1021      1.00    115.00    115.00
ISR01 Z991      MISC LABOUR CODE (INTE RW      W-1021      0.50    115.00     57.50
ARR01 Z992      MISC LABOUR CODE (WARR RW      W-1021      1.00    115.00    115.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.30    115.00     34.50
ARR03 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00        0.00
ARR04 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.20    115.00     23.00
ARR05 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.20    115.00     23.00
      1 WARR      MANUFACTURER WARRANTY RW      W-1021      1.00    115.00    115.00
      1 WARR      MANUFACTURER WARRANTY RW      W-1021      0.50    115.00     57.50
      1 WARR      MANUFACTURER WARRANTY RW      W-1021      0.39    115.00     44.85
      1 WARR      MANUFACTURER WARRANTY RW      W-1021      0.11    115.00     12.65
*****
```

```
*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ISR01  SSE          SHOP SUPPLIES - EXTERNAL W-1021      1.00        0.00        0.00
ISR01  M            MISCELLANEOUS SET OF GLIDE W-1021      1.00       12.00       12.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI          36.37      576.10      0.00        0.00        0.00      612.47
W      1021          0.00      598.00      0.00       12.00        0.00      610.00
*****
```

Continued on page 4

Work Order : 10842

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	36.37	1174.10	0.00	12.00	0.00	1,222.47

&k2S
&k0S