

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10842

Date In:	19 JUL 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11201
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	429LFT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	27 JUL 24	:	:
Delivery Date:	25 DEC 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPU820SP103171	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NTTS    NEW TRAVEL TRAILER STOCK /sold PREP                I    PDI    PRE-D
CEN     CLEAN EXTERIOR- NEW                                I    PDI    PRE-D
ISRO    COMPLAINT:  INTERNAL STOCK REPAIR 01 - Drawer        W    1021   FORES
        damaged in Bedroom, slide crushed it.
        CAUSE:      Slide crushed drawer, found when
                    starting prep. Will need 1.7 to rebuild
                    the drawer, lots of details and time to
                    take apart, cut new boards, fix
                    guides, and put back together. not an
                    average drawer build had to make sure it
                    would not get crushed again so it took a
                    few times and making different cuts, etc
                    to get it to work correctly.
        CORRECTION: Rebuilt drawer, disassembled and cut new
                    sides. Routed indents for base.
                    Reassembled. Replaced slide hardware.
                    Works ok.
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Gas Leak, Manometer W    1021   FORES
        test failed twice
        CAUSE:      Manometer test dropped 1.5psi over 3
                    minutes and 2psi over 5 minutes. Very
                    slow gas leak. Found very small bubbles
                    with soap test at furnace fitting. will
                    need 1 hr for all testing and diagnosing
                    and repairing.
        CORRECTION: Tightened furnace fitting and retested
                    gas leak with nanometer. Tested ok. No
                    more leaking.
```

Continued on page 2

Work Order : 10842

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - wall panel seam in   W    1021   FORES
        CAUSE:      Defective construction 1.5h to repair.
        CORRECTION: Pull 4'length of seam tape off, clean
                    residue from tape.      Reattach wall
                    panels pulling off frame. Pound in
                    staples, add a couple more. Reapply seam
                    tape.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Black markings all   E    1000   GREEN
        CAUSE:      black marks on lino, cannot say what
                    caused it needed .50 to get it all
                    cleaned up
        CORRECTION: cleaned with rag and cleaner.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Bunk wall bracket     W    1021   FORES
        CAUSE:      Screws pulled loose for bunk bracket
                    Will need .20 for repair.
        CORRECTION: Used slightly longer screws to hold
                    bracket in place. Screws were only 1"
                    protrusion into the wall
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Trim in bunkhouse     W    1021   FORES
        CAUSE:      Nails were too far in, nothing to hold
                    trim in place Will need .30 for repair.
        CORRECTION: Pin nailed to secure
1        COMPLAINT:  THE FURNACE IS NOT OPERATING CORRECTLY- W    1021   FORES
        CAUSE:      Furnace not receiving full power from
                    power source. Voltage meter showing
                    10.4v  Furnace only working
                    intermittently. Tested using a 12.7v
                    battery, furnace working fine on
                    dedicated power source.  New power lead
                    needs to be run from distributor box in
                    rear bathroom, to front bedroom where
                    furnace is located. Around 40' A
                    considerable undertaking involving
                    dropping underbelly. (4 hours to fix)
                    Drop underbelly, feed new power wire,
                    test, resecure underbelly.
        CORRECTION: REQUEST 4 HOURS OF LABOR AND 40 FEET OF
                    8G WIRE.

```

```

*****
Job # Part No      Description      PARTS      Bill to  Qty      Price      Total
*****
NTTS  146508        BATTERY BOX GROUP 24      I-PDI      0        8.84        0.00
NTTS  840821034507  12V 24 MDP BATTERY      I-PDI      0        85.20        0.00

```

Continued on page 3

Work Order : 10842

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
CEN   014717396042 HTS STANDARD 10' SEWER H I-PDI      1       7.46       7.46
CEN   019079236326 TOILET TISSUE, SGL. 2 PL I-PDI      1       1.02       1.02
CEN   019079900142 PARK ADAPTER BULK 30-15 I-PDI      1       3.34       3.34
CEN   093344312410 ADAPTER 30 AMP MALE TO 5 I-PDI      1      24.55      24.55
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      1.37     70.00     95.90
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      0.17     70.00     11.90
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      1.41     70.00     98.70
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      0.61     70.00     42.70
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      0.94     70.00     65.80
NTTS  RV1F-1A   NEW STOCK PREP          RW   I-PDI      0.00     70.00      0.00
CEN   CE       CLEAN EXTERIOR          I-PDI      0.00     70.00      0.00
ISR01 Z991     MISC LABOUR CODE (INTE RW   W-1021     1.00    115.00    115.00
ISR01 Z991     MISC LABOUR CODE (INTE RW   W-1021     0.50    115.00     57.50
ARR01 Z992     MISC LABOUR CODE (WARR RW   W-1021     1.00    115.00    115.00
ARR02 Z992     MISC LABOUR CODE (WARR RW   W-1021     0.07    115.00      8.05
ARR02 Z992     MISC LABOUR CODE (WARR RW   W-1021     0.43    115.00     49.45
ARR03 Z992     MISC LABOUR CODE (WARR RW   E-1000     0.00    140.00      0.00
ARR04 Z992     MISC LABOUR CODE (WARR RW   W-1021     0.50    115.00     57.50
ARR05 Z992     MISC LABOUR CODE (WARR RW   W-1021     0.40    115.00     46.00
      1 WARR     MANUFACTURER WARRANTY RW   W-1021     4.00    115.00    460.00
      1 WARR     MANUFACTURER WARRANTY RW   W-1021     0.00    115.00      0.00
      1 WARR     MANUFACTURER WARRANTY RW   W-1021     0.39    115.00     44.85
      1 WARR     MANUFACTURER WARRANTY RW   W-1021     0.11    115.00     12.65
*****
```

```
*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ISR01  SSE         SHOP SUPPLIES - EXTERNAL W-1021     1.00      0.00      0.00
ISR01  M           MISCELLANEOUS SET OF GLIDE W-1021     1.00     12.00     12.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI         36.37      315.00      0.00      0.00      0.00     351.37
W      1021         0.00      966.00      0.00     12.00      0.00     978.00

Totals      36.37     1281.00      0.00     12.00      0.00    1,329.37
*****
```

&k2S
&k0S