

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10911

Date In: 01 AUG 24 Author: KOTT  
Promised Date: 25 DEC 24 Stock No: 11106  
: Year: 2024  
Customer Name: 17376 - IPANIS, DEBORA Manufacturer: FOREST RIVER  
Address: 6119 LOGAN AVENUE SOUT Brand: PUMA TT  
: MINNEAPOLIS, MN Model: 30RKQS  
Postal/Zip: 55419 Miles/Hrs: 0  
Phone#(res): 6127190828 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: 14 JUN 24 :  
Delivery Date: 18 JUL 24 :  
InService Date: :  
Serial#: 4X4TPUF20RP101546 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 CUSTOMER REQUESTS SERVICE CALL TO SITE: 168 WEST E 17376 IPANI  
WALDEN WAY  
2 COMPLAINT: CUSTOMER STATES THAT ENTRY DOOR DOES NOT W 1021 FORES  
CLOSE-  
CAUSE: entry door and screen door are touching  
striker plate pics taken if customer not  
happy with adjustments will need a  
complete entry door assembly. WILL NEED  
1.5 HRS FOR LABOR.  
CORRECTION: adjustments made to framework added  
extra black screws to stop the  
flexibility and sprayed latch with  
silicone the entry door closes  
3 COMPLAINT: CUSTOMER STATES THAT THE SHOWER DOES NOT W 1021 FORES  
FLOW CORRECTLY- CUSTOMER STATES THAT IT  
ALMOST TRICKLES-  
CAUSE: pics taken I found the shower faucet  
spraying all over and not allowing good  
water pressure  
CORRECTION: Will need new shower faucet.... REQUEST  
PN: F100271117 AND 1 HOUR OF LABOR  
4 COMPLAINT: CUSTOMER STATES THAT THE BEDROOM AND THE W 1021 FORES  
BATHROOM DOOR DO NOT STAY OPEN PROPERLY-  
CUSTOMER STATES THAT THE SEEM "TIGHT" IN  
THE FRAME- CUSTOMER WOULD LIKE TO HAVE  
LOOKED AT-  
CAUSE: found camper a little uneven and some  
screws loose on hinges on bedroom and

Continued on page 2

Work Order : 10911

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                bathroom door loose WILL NEED .5 FOR
                REPAIRS
CORRECTION: relevel camper and tighten hinges  both
doors are working
WARR    COMPLAINT:  MFG RECALL 51-1744 The Alpha Roof           W    1021    FORES
                Sealant may cause the Solar Panel Inlet
                to crack, which may allow water
                intrusion.
CAUSE:    MFG RECALL.

```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty  Price  Total
*****
2      822001416 DOOR, ENTRY, 26" X 72" RADI W-1021      0    361.84  0.00
3      822071117 FAUCET, SHOWER, TWO HANDLE, W-1021      0    10.82  0.00

```

```

*****
Job#  Lab Code  Description           LABOUR  Mech Bill to  Hrs  Rate  Total
*****
2  Z991      MISC CODE (NTERNAL)  JS  W-1021      0.70  115.00  80.50
3  WARR      MANUFACTURER WARRANTY JS  W-1021      0.50  115.00  57.50
4  WARR      MANUFACTURER WARRANTY JS  W-1021      0.40  115.00  46.00
ARR01 Z992      MISC LABOUR CODE (WARR W-1021      0.00  115.00  0.00

```

```

*****
Job #  Excode  Description           EXTRAS           bill to  Qty  Price  Total
*****
1  SSE      SHOP SUPPLIES - EXTERNAL E-17376  1.00  0.00  0.00
1  SC      SERVICE CALL           E-17376  0.00  3.75  0.00
1  SC      SERVICE CALL           E-17376  0.00  3.75  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id           Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021                0.00   184.00   0.00   0.00   0.00  184.00

Totals                0.00   184.00   0.00   0.00   0.00  184.00

```

&k2S  
&k0S