

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10946B

Date In: 20 AUG 24 Author: KOTT
Promised Date: 31 DEC 24 Stock No: 11217
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: TRANSCEND XPLOR
: WISCONSIN RAPIDS, WI Model: 26BHX
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: PI SUB. 8/20 ON GD
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TT3126S8833188 :

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. DIRT OR SAND ON I PDI PRE-D
CEILING IN MIDDLE OF LIVING ROOM AROUND
LIGHT 2. SCAPE IN UPPER RIGHT SLIDE
FACIA
CAUSE: Daf
CORRECTION: The sawdust wiped right off and the
scrape is on warranty line 2
WARR COMPLAINT: WARRANTY REPAIR 1 - roof has one bubble W 1020 GRAND
in sealant
CAUSE: Bubble in dicor from mfg
CORRECTION: Popped bubble cleaned then filled with
dicor
WARR COMPLAINT: WARRANTY REPAIR 2 - small knicks in wood W 1020 GRAND
throughout unit visible staple holes
throughout unit
CAUSE: Knicks in wood WILL NEED .80 TO FILL ALL
HOLES IN UNIT.
CORRECTION: Used putty for fill knicks in
WARR COMPLAINT: WARRANTY REPAIR 3 - water heater seam is W 1020 GRAND
not sealed
CAUSE: Mfg did not seal . WILL NEED .50 TO
COMPLETELY SEAL WATER HEATER.
CORRECTION: Used clear sealant to cover the seam on
exterior water heater
WARR COMPLAINT: WARRANTY REPAIR 5 - awning goes thump as W 1020 GRAND
it rolls out
CAUSE: Bad motor Please order new head with
motor for awning VELARIUM m#VP17110000

Continued on page 2

Work Order : 10946B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                               S#895077
CORRECTION: ..... REQUEST 2 HOURS OF LABOR
REQUEST PN:
WARR    COMPLAINT: WARRANTY REPAIR 6 - thermostat has no      W    1020    GRAND
          power to it , worked Friday not even
          able to turn thermostat on on Monday
CAUSE:   Loose wire behind thermostat  No pic
          taken it NEED .10 FOR REPAIR.
CORRECTION: SECURED WIRE AND WORKING AS IT SHOULD.
WARR    COMPLAINT: WARRANTY REPAIR 8 - the cabinet floor of W    1020    GRAND
          right hand cabinet above kitchen sink is
          not level .
CAUSE:   Improper install. JUST NOTING NOT FIXED
          AT THIS TIME.
CORRECTION: PLEASE NOTE WITH MFG IN CASE FUTURE
          CUSTOMER IS WANTING THIS REDONE

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
DAF Z991 DAF-WARRANTY REPAIR HOD I-PDI 0.10 70.00 7.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 115.00 11.50
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.60 115.00 69.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 115.00 0.00
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 115.00 11.50
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 115.00 0.00
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.40 115.00 46.00
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 115.00 0.00
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 115.00 0.00
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 115.00 0.00
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 115.00 11.50
ARR08 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 115.00 11.50

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I PDI 0.00 7.00 0.00 0.00 0.00 7.00
W 1020 0.00 161.00 0.00 0.00 0.00 161.00
Totals 0.00 168.00 0.00 0.00 0.00 168.00

```

Continued on page 3

Work Order : 10946B

&k2S
&k0S