

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11044

Date In: 23 AUG 24 Author: MGRAY
Promised Date: 23 AUG 24 Stock No: 11039
: Year: 2024
Customer Name: 17347 - DEAN, CHAD Manufacturer: GRAND DESIGN
Address: 3954 GREEN BRIAR CT Brand: REFLECTION 100 SERIES
: NEKOOSA, WI Model: 27BH
Postal/Zip: 54457 Miles/Hrs: 0
Phone#(res): 7156976449 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: ldrski45@gmail.com Tag#:
Purchased Date: 25 MAY 24 :
Delivery Date: 05 JUN 24 :
InService Date: :
Serial#: 573FR3325R3348802 :

```
*****  
Job # Description JOB INFORMATION Type Bill To  
*****  
WARR COMPLAINT: WARRANTY REPAIR 1 - COMPARTMENT DOORS, W 1020 GRAND  
RIGHT FRONT, ARE WARPED. THEY LATCH BUT  
IT DOESN'T SEAL PROPERLY.  
CAUSE: COMPLARTMENT DOOR IS WARPED AND NEED  
REPLACEMENT. DOOR IS 34.5X25 NEED 1.5  
LABOR FOR R&R  
WARR COMPLAINT: WARRANTY REPAIR 2 - CABINET DOOR ABOVE W 1020 GRAND  
THE COUCH IS WARPED AND SAGGING.  
CAUSE: CABINET DOOR ON ODS OF UNIT IS WARPED  
AND NOT CLOSING PROPERLY. NEED  
REPLACEMENT. DOOR MEASUREMENTS ARE NEED  
.5 TO R&R CABINET DOOR.  
WARR COMPLAINT: WARRANTY REPAIR 3 - CRACKED TAIL LIGHT W 1020 GRAND  
ON RIGHT SIDE. WORKS PROPERLY BUT THE  
BOTTOM IS CRACKED.  
CAUSE: TAIL LIGHT COVER IS CRACKED ON THE  
BOTTOM LEFT CORNER OF LIGHT, NEED  
REPLACEMENT. NEED .5 LABOR TO R&R LIGHT  
COVER AND RESEAL  
WARR COMPLAINT: WARRANTY REPAIR 4 - CLEARANCE LIGHT W 1020 GRAND  
RIGHT FRONT ONLY 2 OUT OF 3 BULBS ARE  
WORKING PROPERLY. LED LIGHT.  
CAUSE: CLEARANCE LIGHT HAS THREE BULBS, ONE  
BULD IS OUT. LIGHT IS A LED AND NEEDS  
COMPLETE REPLACMENT. NEED .3 TO R&R  
LIGHT  
WARR COMPLAINT: WARRANTY REPAIR 5 - PANEL IN THE REAR OF W 1020 GRAND  
THE EXTERIOR OF UNIT, SCREW WAS
```

Continued on page 2

Work Order : 11044

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                TIGHTENED TOO MUCH AND CRACKED.
CAUSE:   FACISA ON ODS SLIDE OUT BOTTOM RIGHT
                CORNER IS CRACKED AND NEED
                REPLACEMENT.WILL NEED .30 FOR REPAIR AND
                REPLACEMENT FASCIA.
WARR    COMPLAINT:  WARRANTY REPAIR 6 - ROLLER FOR LATCH ON W    1020    GRAND
                BOTTOM DRAWER DS OF UNIT NEXT TO DOOR IS
                MISSING. DRAWER DOES NOT LATCH PROPERLY.

CAUSE:   LATCH FOR DRAWER IS MISSING ONE ROLLER
                ON THE RIGHT HAND SIDE, CAUSEING DRAWER
                NOTG TO LATCH. NEEDS REPLACEMENT LATCH.
                NEED .2 TO REPLACE
    
```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty  Price  Total
*****
WARR0 822061004 DOOR BAGGAGE DRLUG08 34 1/2 W-1020      0  224.03  0.00
WARR0 82200422 S/O BOTTOM CAP TALL BLACK W-1020      0  11.18  0.00
WARR0 109672 CATCH DOOR W-1020      0  0.44  0.00
WARR0 822020997 LIGHT LED AMBER MARKER SIDE W-1020      0  6.01  0.00
WARR0 420855 LIGHT REAR 6" OVAL LED 7 DI W-1020      0  9.62  0.00
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 RV31B-4 COMPARTMENT DOOR R&R ( W-1020 0.00 115.00 0.00
ARR02 I230 DOOR, CABINET, R & R W-1020 0.00 115.00 0.00
ARR03 RV9AI-20 TAIL LIGHT R&R SURFACE W-1020 0.00 115.00 0.00
ARR04 E180 CLEARANCE LIGHT, EXTER W-1020 0.00 115.00 0.00
ARR05 Z992 REPLACE CRACKED EXTERI W-1020 0.00 115.00 0.00
ARR06 I410 LATCH, CABINET, R & R W-1020 0.00 115.00 0.00
    
```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
Totals 0.00 0.00 0.00 0.00 0.00 0.00
    
```

&k2S
&k0S