

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11044

Date In: 23 AUG 24 Author: MGRAY
Promised Date: 15 SEP 24 Stock No: 11039
: Year: 2024
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN
Address: 11333 COUNTY RD 2 Brand: REFLECTION 100 SERIES
: MIDDLEBURY, IN Model: 27BH
Postal/Zip: 46540 Miles/Hrs: 0
Phone#(res): 888-825-2820 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: db 8/24
Purchased Date: 25 MAY 24 :
Delivery Date: 05 JUN 24 :
InService Date: :
Serial#: 573FR3325R3348802 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - COMPARTMENT DOORS, W 1020 GRAND
RIGHT FRONT, ARE WARPED. THEY LATCH BUT
IT DOESN'T SEAL PROPERLY.
CAUSE: COMPARTMENT DOOR IS WARPED AND NEED
REPLACEMENT. DOOR IS 34.5X25 NEED 1.5
LABOR FOR R&R
WARR COMPLAINT: WARRANTY REPAIR 2 - CABINET DOOR ABOVE W 1020 GRAND
THE COUCH IS WARPED AND SAGGING.
CAUSE: CABINET DOOR ON ODS OF UNIT IS WARPED
AND NOT CLOSING PROPERLY. NEED
REPLACEMENT. DOOR MEASUREMENTS ARE NEED
.5 TO R&R CABINET DOOR.
WARR COMPLAINT: WARRANTY REPAIR 3 - CRACKED TAIL LIGHT W 1020 GRAND
ON RIGHT SIDE. WORKS PROPERLY BUT THE
BOTTOM IS CRACKED.
CAUSE: TAIL LIGHT COVER IS CRACKED ON THE
BOTTOM LEFT CORNER OF LIGHT, NEED
REPLACEMENT. NEED .5 LABOR TO R&R LIGHT
COVER AND RESEAL
WARR COMPLAINT: WARRANTY REPAIR 4 - CLEARANCE LIGHT W 1020 GRAND
RIGHT FRONT ONLY 2 OUT OF 3 BULBS ARE
WORKING PROPERLY. LED LIGHT.
CAUSE: CLEARANCE LIGHT HAS THREE BULBS, ONE
BULD IS OUT. LIGHT IS A LED AND NEEDS
COMPLETE REPLACMENT. NEED .3 TO R&R
LIGHT
WARR COMPLAINT: WARRANTY REPAIR 5 - PANEL IN THE REAR OF W 1020 GRAND
THE EXTERIOR OF UNIT, SCREW WAS

Continued on page 2

Work Order : 11044

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                TIGHTENED TOO MUCH AND CRACKED.
CAUSE:    FACISA ON ODS SLIDE OUT BOTTOM RIGHT
                CORNER IS CRACKED AND NEED
                REPLACEMENT.WILL NEED .30 FOR REPAIR AND
                REPLACEMENT FASCIA.
WARR    COMPLAINT:  WARRANTY REPAIR 6 - ROLLER FOR LATCH ON W    1020    GRAND
                BOTTOM DRAWER DS OF UNIT NEXT TO DOOR IS
                MISSING. DRAWER DOES NOT LATCH PROPERLY.

CAUSE:    LATCH FOR DRAWER IS MISSING ONE ROLLER
                ON THE RIGHT HAND SIDE, CAUSEING DRAWER
                NOTG TO LATCH. NEEDS REPLACEMENT LATCH.
                NEED .2 TO REPLACE
WARR    COMPLAINT:  WARRANTY REPAIR 7 - TOOK SHOWER IN UNIT W    1020    GRAND
                AND IT FLOODED THE LIVING ROOM AREA.
                LOOKS TO BE HAVING WATER COME OUT FROM
                BEHIND THE COUCH. THERE IS A TRIM BOARD
                ON THE BOTTOM OF THE WALL BEHIND COUCH
                IS WHERE A MAJORITY OF THE WATER WAS
                FOUND. THERE WAS ALSO SOME IN THE CORNER
                OF THE SLIDE OUT NEXT TO THEM.

CAUSE:    test shower for water leak into living
                room. unit is a fifthwheel. shower is up
                stairs. when testing for leak, found
                nothing until i put 2 bricks in in the
                shower pan. then it leaked into living
                room really bad. shower suround not
                sealed around the shower pan. will need
                to dry it all out then fasten surround
                to wall better, then seal around base.
                will need 3 hours to complete task.

CORRECTION: wait for approval.
    
```

```

*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
WARR0 822061004 DOOR BAGGAGE DRLUG08 34 1/2 W-1020 0 224.03 0.00
WARR0 EST 663621 - door cabinet 13x33 W-1020 0 0.00 0.00
WARR0 420855 LIGHT REAR 6" OVAL LED 7 DI W-1020 0 9.62 0.00
WARR0 822020997 LIGHT LED AMBER MARKER SIDE W-1020 0 6.01 0.00
WARR0 82200422 S/O BOTTOM CAP TALL BLACK W-1020 0 11.18 0.00
WARR0 109672 CATCH DOOR W-1020 0 0.44 0.00
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 RV31B-4 COMPARTMENT DOOR R&R ( TD W-1020 0.00 115.00 0.00
ARR02 I230 DOOR, CABINET, R & R TD W-1020 0.00 115.00 0.00
ARR03 RV9AI-20 TAIL LIGHT R&R SURFACE TD W-1020 0.00 115.00 0.00
    
```

Continued on page 3

Work Order : 11044

```
*****
Job#  Lab Code  Description      LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR04 E180      CLEARANCE LIGHT, EXTER TD    W-1020    0.00   115.00    0.00
ARR05 Z992      REPLACE CRACKED EXTERI TD    W-1020    0.00   115.00    0.00
ARR06 I410      LATCH, CABINET, R & R TD    W-1020    0.00   115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR TD    W-1020    0.00   115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR TD    W-1020    0.50   115.00   57.50
ARR07 Z992      MISC LABOUR CODE (WARR TD    W-1020    0.00   115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR TD    W-1020    0.00   115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR TD    W-1020    0.00   115.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020          0.00    57.50     0.00     0.00     0.00    57.50
*****
Totals          0.00    57.50     0.00     0.00     0.00    57.50
*****
```

&k2S
&k0S