

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2080589
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUNB7P4018079
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$115.00	ITEM #	PUT24FBSC-425
OWNER INFORMATION		DEALER RO #	11262
DAVID HUFF		CLAIM START DATE	10/03/2024
1131 90th St S		CLAIM END DATE	10/04/2024
Wisconsin Rapids, WI 54494			
USA			
Retail Date of Purchase	03/12/2024	WARRANTY EXPIRATION DATE	03/12/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-136-24-00-001484	Fresh Water Fill Hose - Plumbing/Fresh Water Supply/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-10-03 14:14:45 :: Complaint: Fill hose is kinked and needs to be straightened out for easier filling of tank. Cause: Hose to fresh tank is definitely kinked, looks to be too much extra line and it loops a couple time before connecting to the tank. Correction: Using a different style fitting as there is minimal clearance to work in. Removed 18" of hose, fits better without kinking. Tested okay, no leaks. Spray foam to finish.			
Model#		Dlr Sub Hrs	1.50	Sub Labor Amt \$172.50
Serial#		Appr Hrs	1.50	Appr Labor Amt \$172.50
	Notes			
	is this hose to the city water connection ??			
	Tech notes say fill hose to the fresh water tank.			

Part

Line# 1	Item #	Description			
	USERPART	742979168038- 1PC 1/2 x 1/2 elbow			
	Model #	Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.56	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.56	Appr Freight \$0.00
	Notes				

Submitted	Labor Amt	\$172.50	Approved	Labor Amt	\$172.50
	Parts & Freight	\$2.56		Parts & Freight	\$2.56
	Total	\$175.06		Total	\$175.06

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.