

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11492

Date In:	19 OCT 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11280
:	:	Year:	2025
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE
:	MIDDLEBURY, IN	Model:	2670MK
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	STOCK PREP
Purchased Date:		:	:
Delivery Date:		:	:
InService Date:		:	:
Serial#:	573TE3228S6652842	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
NTTS    COMPLAINT: NEW TRAVEL TRAILER STOCK PREP          I    PDI    PRE-D
        CAUSE: New unit
        CORRECTION: Complete
CEN     COMPLAINT: CLEAN EXTERIOR- NEW                      I    PDI    PRE-D
        CAUSE: Ods slide inop. No power coming from
        control board. Wire severed in between
        the board and the motor.
        CORRECTION: Ran new power wire from the board to the
        motor in the underbelly system.
WS      COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF    I    PDI    PRE-D
        CONTAINED - TOWABLE
        CAUSE: New prep
        CORRECTION: Completed
WARR    COMPLAINT: WARRANTY REPAIR 1 - ODS DINNETTE SLIDE  W    1020  GRAND
        OUT HAS ISSUE. HAD TO BE MANUALLY PUT
        IN.
        CAUSE: Ods dinette slide will not come in or
        out. When pressing the button on panel,
        it gives several flashes indicating
        there is a problem.
        CORRECTION: Had to disconnect hot wire from control
        box and run a new one from control box
        to slide motor. Slide works good now.
        Will need to drop underbelly later when
        unit is to be prepped to get pictures of
        bad wire.
WARR    COMPLAINT: WARRANTY REPAIR 2 - bubbles in dicor on  W    1020  GRAND
        roof
*****
```

Continued on page 2

Work Order : 11492

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:      Mfg
CORRECTION: Popped the bubbles and Cleaned and
              sealed the areas that had bubbles
WARR    COMPLAINT:  WARRANTY REPAIR 3 - ods front black   W    1020   GRAND
              metal has a divet in it
CAUSE:      Looks as though rocks hit the metal and
              made divers in 2 spots Put in for
              preauth if approved would like to order
              black textured metal for front bottom of
              the unit  measures 96" wide 26"tall with
              1"bend at the bottom
CORRECTION: .....
WARR    COMPLAINT:  WARRANTY REPAIR 4 - the bottom black   W    1020   GRAND
              metal rock guard has 2 divers where
              rocks hit it in transportation to here I
              believe
CAUSE:      Looks like a couple rocks hit the black
              bottom front metal  Get preauth to
              change metal measures 96" wide x 26"
              tall with 1" bend at bottom please order
              if approved
CORRECTION: .....
WARR    COMPLAINT:  WARRANTY REPAIR 5 - SLIDE OUT IS NOT   W    1020   GRAND
              WORKING PROPERLY. DIAGNOSE.
CAUSE:      Ods quit working. Checked all
              connections at controller and motor. All
              connections were good. Used a battery
              direct to motor, and it still would not
              work. Motor is bad. Need new motor and
              possibly controller. Pics uploaded.
              REQUEST 1.5 HOURS FOR LABOR
CORRECTION: ...
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI           0     7.55    0.00
WARR0 822070087     SLIDEOUT ACTUATOR 40" W/ W-1020           0   557.96    0.00
    
```

```

*****
Job# Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
NTTS RV1F-1A  NEW STOCK PREP           HOD I-PDI           0.00  70.00    0.00
NTTS RV1F-1A  NEW STOCK PREP           HOD I-PDI           0.46  70.00   32.20
NTTS RV1F-1A  NEW STOCK PREP           HOD I-PDI           2.54  70.00  177.80
NTTS RV1F-1A  NEW STOCK PREP           HOD I-PDI           1.50  70.00  105.00
CEN CE        CLEAN EXTERIOR           TD I-PDI            0.10  70.00    7.00
WS W495       WINTERIZE RV (WATER SY HOD I-PDI           0.70  70.00   49.00
ARR01 Z992     MISC LABOUR CODE (WARR TD W-1020           0.00 115.00    0.00
    
```

Continued on page 3

Work Order : 11492

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   115.00   57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR05 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.00   115.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.02   115.00    2.30
ARR05 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.11   115.00   12.65
ARR05 Z992      SLIDE OUT ACTUATOR          W-1020    0.00   115.00    0.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR02  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I    PDI            0.00    371.00    0.00    0.00    0.00    371.00
W    1020           0.00    244.95    0.00    0.00    0.00    244.95
      Totals       0.00    615.95    0.00    0.00    0.00    615.95
*****
```

&k2S
&k0S