

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2241286
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TFLF20S1907800
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010C
 ITEM # FLT826MBR
 DEALER RO # 11576B
 CLAIM START DATE 03/25/2025
 CLAIM END DATE 03/26/2025

Labor rate: \$140.00
 OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-03-25 13:26:26 :: Complaint: The light above the bed flickers on and off. Cause: Possible loose wiring. Correction: Dropped light, checked connections, all good, turned on and off many times then left light on and it has not flickered at all. Additional Note : greeneway@dealer-advisors.com, 2025-03-25 13:28:08 :: This is the only Light REPAIR code I could find.
 Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$70.00
 Serial# Appr Hrs 0.50 Appr Labor Amt \$70.00
Notes
 authorized to repair wiring.

Labor

Line# 2 **Operation Code** **Operational Description**
 30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-03-25 13:29:04 :: Complaint: Trim above sofa near ceiling is uneven. Cause: Trim is loose. Correction: Tapped trim back into place then used matching putty to fill the space where the two trim pieces meet.
 Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$28.00
 Serial# Appr Hrs 0.20 Appr Labor Amt \$28.00
Notes
 authorized to repair trim.

Labor

Line# 3 **Operation Code** **Operational Description**
 30-91-01-00-000901 Rocker, Recliner, or Glider Chair - Interior/Living Quarters, Sofa, Chair/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-03-25 13:29:55 :: Complaint: Emergency window opener hits recliner back when trying to open. Cause: Recliners are too close to windows. Correction: Noting for now. Additional Note : greeneway@dealer-advisors.com, 2025-03-25 13:30:39 :: No repair/adjust code to choose for recliner.
 Model# Dlr Sub Hrs 0.00 Sub Labor Amt \$0.00
 Serial# Appr Hrs 0.00 Appr Labor Amt \$0.00
Notes
 noting for now. Thank you.

Submitted Labor Amt \$98.00
 Parts & Freight \$0.00

Approved Labor Amt \$98.00
 Parts & Freight \$0.00

Total \$98.00

Total \$98.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.