

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 11589

Date In:	12 NOV 24	Author:	MGRAY
Promised Date:	19 NOV 24	Stock No:	11130
:	:	Year:	2024
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	TRANSCEND XPLOR
:	MIDDLEBURY, IN	Model:	221RB
Postal/Zip:	46540	Miles/Hrs:	
Phone#(res):	888-825-2820	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:	22 JUN 24	:	:
Delivery Date:	26 JUL 24	:	:
InService Date:		:	:
Serial#:	573TT2721R8831375	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - THERE IS TRIM MOLDING IN THE UNIT THAT IS FALLING DOWN AND NEEDS TO BE PINNED BACK UP. TRIM AROUND THE TOP OF THE DINNETTE.	W	1020 GRAND
	CAUSE:	Top trim boards on the back of both dinette seats fell off.		
	CORRECTION:	Reinstall trim boards.		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - BROKEN SLIDE OUT DRAWER IN SLIDE OUT. DRAWER UNDER REFER.	W	1020 GRAND
	CAUSE:	Drawer glide under refer loosened up on right. Has loose screws.		
	CORRECTION:	Installed new screws. Tested good.		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - THERE IS A HOLE BY THE SLIDE OUT THAT YOU CAN SEE LIGHT OUT OF. UNSURE IF THERE IS A MISSING SEAL OR SOMETHING. IT IS NOT HAPPENING ON THE OTHER SIDE OF THE SLIDE BY THE REFER. LOOKS LIKE THE SEAL IS FALLING DOWN. BOTTOM OF THE SLIDEOUT BY FLOOR.	W	1020 GRAND
	CAUSE:	Check slide seals for gaps. Rear ods sweeper seal on left side is short of going down to floor causing a void to see daylight. Need new seal install. Would have to remove facia to replace seal. 1 hour labor.		
	CORRECTION:	...		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - FREEZER DOOR DOES NOT LOCK. OPENING DURING TRAVEL.	W	1020 GRAND

Continued on page 2

Work Order : 11589

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Doors for refer don't latch.
CORRECTION: Adjusted doors so that they latch.
          Tested good.
WARR    COMPLAINT:  WARRANTY REPAIR 5 - DS SIDE LATCH TO THE W   1020   GRAND
          GARAGE DOES NOT LATCH JUST SPINS AROUND.

CAUSE:   Ds compartment latch is loose in front.
CORRECTION: Tighten screw that holds the striker.
          Tested good.

```

```

*****
Job # Part No Description           PARTS           Bill to   Qty   Price   Total
*****
WARR0 82200426 SEAL SLIDEOUT 2 3/4 BLACK WI W-1020      0     2.98     0.00

```

```

*****
Job# Lab Code Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020    0.39  115.00  44.85
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1020    0.50  115.00  57.50
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1020    0.50  115.00  57.50
ARR04 Z992 MISC LABOUR CODE (WARR TD W-1020    0.50  115.00  57.50
ARR05 Z992 MISC LABOUR CODE (WARR TD W-1020    0.50  115.00  57.50
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020    0.11  115.00  12.65

```

CUSTOMER COMMENTS

```

*****
GRAND DESIGN ORDER # 1190135

```

BILLINGS SUMMARY

```

*****
Type Bill Id      Parts   Labour   Sublet   Extras   Tax   Total
*****
W      1020           0.00   287.50   0.00    0.00   0.00   287.50
          Totals           0.00   287.50   0.00    0.00   0.00   287.50

```

&k2S
&k0S