

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2203671
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4FFLN27S1908134
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$115.00	SITE/WAREHOUSE	010 / 010C
OWNER INFORMATION		ITEM #	FLFF361RLS
		DEALER RO #	11696
		CLAIM START DATE	02/18/2025
		CLAIM END DATE	06/10/2025
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Line# 3	Operation Code	Operational Description
	30-100-01-00-001053	Closet Clothes Rod - Interior/Cabinetry/Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : greeneway@dealer-advisors.com, 2025-02-18 13:54:05 :: Complaint: Coat rack in the bedroom	

closet is bent. Cause: From factory. Correction: Replace coat rack.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50

Serial# Appr Hrs 0.50 Appr Labor Amt \$57.50

Notes

bvdillon

Part

Line# 1

Item #

F100459801

Description

CLOSET ROD - PFL: BLACK - 32" - V# 23-1185-16 | X

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$8.00

Sub Freight \$18.31

Appr Qty 1.00

Appr Dlr Price \$8.00

Appr Freight \$18.31

Notes

Labor

Line# 4

Operation Code

30-100-24-00-001054

Operational Description

Kitchen/Galley Countertop - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-18 13:55:48 :: Complaint: There is a chip on the back side of the island in the kitchen. Cause: From Manufacturer. Correction: Need to use putty to fix the chip in island and a paint pen to match the color.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$57.50

Serial# Appr Hrs 0.50 Appr Labor Amt \$57.50

Notes

bvdillon

Labor

Line# 5

Operation Code

60-136-01-00-002002

Operational Description

Water Line Shut-Off Valve - Plumbing/Fresh Water Supply/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-18 13:57:04 :: Complaint: The water line connectors for the washer in the bedroom are leaking. Cause: Bad connector for the washer line. Correction: Replace connector. Additional Note : greeneway@dealer-advisors.com, 2025-02-18 13:57:41 :: Unsure on correct labor code to replace connector.

Model# Dlr Sub Hrs 0.00 Sub Labor Amt \$0.00

Serial# Appr Hrs 0.50 Appr Labor Amt \$57.50

Notes

can you please email us the video at rockwoodflagstaffauths@forestriverinc.com
Video has been emailed. Thank you.
authorized to replace connector.

Part

Line# 1

Item #

USERPART

Description

4809281 wash machine vlv pex 1/2"

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$23.39

Sub Freight \$0.00

Appr Qty 1.00

Appr Dlr Price \$23.39

Appr Freight \$0.00

Notes

Submitted

Labor Amt \$161.00

Parts & Freight \$64.78

Total \$225.78

Approved

Labor Amt \$212.75

Parts & Freight \$64.78

Total \$277.53

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.

