

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11696

Date In:	23 JAN 25	Author:	MGRAY
Promised Date:	04 JUL 25	Stock No:	11313
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	FLAGSTAFF CLASSIC FW
:	WISCONSIN RAPIDS, WI	Model:	361RLS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4FFLN27S1908134	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
CEN	CLEAN EXTERIOR- NEW		I	PDI PRE-D
NFWS	NEW FIFTH WHEEL STOCK PREP		I	PDI PRE-D
WS	WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - TOWABLE		I	PDI PRE-D
WARR	COMPLAINT: WARRANTY REPAIR 1 - PIECE OF TRIM CAM OFF LEFT FRONT SIDE OF THE BED. CAUSE: WILL NEED TO RENAIL THE PIECE OF TRIM BACK ONTO THE BED CORRECTION: REQUESTING .30 FOR LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 2 - WINDOW IN BEDROOM HAS A BEND IN PART OF THE FRAME WHERE THE TWO WINDOWS MEET CAUSE: NOTING FOR MFG		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 3 - RUBBER STOPPER MISSING FROM STOVE FOR THE GRILL COVERS CAUSE: MFG		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 4 - COAT RACK IN THE BEDROOM CLOSET IS BENT CAUSE: NEED TO TRY AND BEND BACK INTO PLACE OR REPLACE COAT RACK CORRECTION: REQUESTING .50 FOR LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 5 - CHIP ON THE BACK SIDE OF THE ISLAND IN THE KITCHEN CAUSE: FROM MFG CORRECTION: REQUESTING .50 FOR LABOR		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 6 - NOTING THAT THERE ARE SCRATCHES IN THE SINK CAUSE: MFG		W	1021 FORES

Continued on page 2

Work Order : 11696

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
WARR      COMPLAINT:  WARRANTY REPAIR 7 - THE WATER LINE      W      1021      FORES
              CONNECTORS FOR THE WASHER IN THE BEDROOM
              ARE LEAKING
      CAUSE:      BAD CONNECTOR FOR THE WASHER LINE WHICH
              WAS CAUSING TE LEAK. NEED TO REPLACE
      CORRECTION: REQUESTING 1 HOUR LABOR

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON I-PDI      0      7.55      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
CEN CE      CLEAN EXTERIOR      I-PDI      0.00      70.00      0.00
NFWS RV1F-1A NEW STOCK PREP      I-PDI      0.00      70.00      0.00
WS W495      WINTERIZE RV (WATER SY      I-PDI      0.00      70.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR05 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR      W-1021      0.00      115.00      0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
Totals      0.00      0.00      0.00      0.00      0.00      0.00

```

&k2S
&k0S