



Warranty Claim Form

Date: 3/13/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3121S8836242
Transcend 26BHX
Retail Purchase Date: null
Work Started: 2/26/2025
Work Completed: 2/26/2025

Claim Status: Paid
Dealer Work Order #: 11697
Unit Offline Date: 12/16/2024

Claim #: 877908
Labor: \$230.00
Parts: \$0.00
Shipping: \$0.00
Total: \$230.00

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 220004 Quick Connects & Valves - Locate & *Fault Code:* Improper Installation/Build Tighten**

Problem: Noticed during prep that the screws had broken off the quick disconnect.

Hours: .7

Cause: The screws that hold the quick disconnect to the frame snapped off.

Amount: 80.50

Remedy: Removed the broken screws that were still in the frame and reattached with new screws.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 570041 Slide Room Exterior Fascia - Reseal - *Fault Code:* Damaged/Maintenance Cap Seal

Problem: Silicone around bulb seals is bubbled and missing silicone. It has holes in it.

Hours: .5

Cause: Bulb seal around the slide out has holes in the silicone from manufacturing.

Amount: 57.50

Remedy: Resealed around bulb seal with clear silicone to cover up the holes so now it is completely sealed.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 650002 Base Cabinets - Repair Base *Fault Code:* Improper Installation/Build Cabinet

Problem: Noticed during prep that there were staples poking through in the kitchen.

Hours: .3

Cause: Staple popping up in the cabinet from install.

Amount: 34.50

Remedy: Removed staple and filled with putty.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 4

Flat Rate Code: 110017 Underbelly - Resecure

Fault Code: Improper Installation/Build

Problem: Underbelly has a gap where the gas line is.

Hours: .5

Cause: LP line and underbelly are hanging down and has gaps, wasn't properly installed.

Amount: 57.50

Remedy: Added one more LP clamp and self-tapping screw. It is all sealed up now.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: