

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2390190  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4FFLN26S1908190  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010C  
 ITEM # FLFF371RK  
 DEALER RO # 11724  
 CLAIM START DATE 08/04/2025  
 CLAIM END DATE 08/07/2025

Labor rate: \$140.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 20-73-19-00-000739      Fenderskirt - Exterior/Fender Skirts, Wheel Well/Reseal/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:04:49 :: Complaint: Both fender skirts are separating from the paneling in the middle. Cause: Both fender covers were starting to separate in the middle. Correction: Re-applied silicone.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$42.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$42.00

**Notes**  
 Hello, the repair code has been updated to a more appropriate one based on the root cause of the issue.

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 30-102-01-00-001096      Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:06:07 :: Complaint: White trim on the top of the stairs is cracked. Cause: At the top of the inside stairs there is a piece of trim on the right on the floor that has a crack going across it. Correction: Put putty over it. Additional Note : greeneway@dealer-advisors.com, 2025-08-04 21:06:45 :: No repair code for trim.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$42.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$42.00

**Notes**  
 authorized to repair

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-102-01-00-001096      Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-08-04 21:07:49 :: Complaint: Trim in the bedroom closet in the hole to the washer and dryer is cracked on the bottom from a staple poking out. Cause: Staple cracked the trim. Correction: Glued down the extra tape and put putty over it. Additional Note : greeneway@dealer-advisors.com, 2025-08-04 21:08:07 :: No repair code

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$42.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$42.00

**Notes**  
 bvdillon

### Labor

**Line# 4**      **Operation Code**      **Operational Description**

