

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11730

Date In: 10 FEB 25 Author: MGRAY
Promised Date: 04 JUL 25 Stock No: 11316
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION
: WISCONSIN RAPIDS, WI Model: 16BHCE
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: 22 APR 25 :
Delivery Date: 02 MAY 25 :
InService Date: :
Serial#: 5ZT2PU EC2S4023286 :

Job #	Description	JOB INFORMATION	Type	Bill To
NTTS	COMPLAINT: NEW TRAVEL TRAILER STOCK PREP		I	PDI PRE-D
	CORRECTION: STOCK PREP			
1	COMPLAINT: FOUND ON PREP- THE FURNACE VENT IS DISCOLORED-		W	1021 FORES
	CAUSE: Exterior furnace vent needs polishing and new screws. Corroded due to salt. NEED .80 FOR REPAIR			
	CORRECTION: Used an red scotch bright scrubbing pad and some automotive polish, installed six new black screws. Like new.			
2	COMPLAINT: FOUND ON PREP- THE TOP OF THE BATHROOM DOOR HAS A CHIP IN IT-		W	1021 FORES
	CAUSE: Black finish bathroom door, chip in the finish on top. Mishandling at the factory. NEED .20 FOR REPAIR			
	CORRECTION: Sanded edges of tear, smoothed it out and covers with marker. Black paint marker covered it up.			
3	COMPLAINT: FOUND ON PREP- THERE ARE FIBERS STICKING OUT ALL OVER THE COUCH-		W	1021 FORES
	CAUSE: Upholstery stitches have leftover excess on futon couch. NEED .20 TO REMOVE EXCESS FIBERS.			
	CORRECTION: Cut fibers off with scissors			
4	COMPLAINT: FOUND ON PREP- THERE IS A KNICK IN THE STYLE UNDER THE BED-		W	1021 FORES
	CAUSE: Cabinet doors under bottom bunk, bottom style board has knick along with factory			

Continued on page 2

Work Order : 11730

Job #	Description	JOB INFORMATION	Type	Bill To
		red tape. Need 6" matching seam tape to fix damage. Light Grey woodgrain color. Panel board under main mattress has damage, unknown cause, Likely manufacturer flaw. Order 4x8 of matching type and/or seam tape to match. Light Grey woodgrain pattern. WILL NEED .50 FOR REPAIR		
5	CORRECTION: ... noting for now- COMPLAINT: FOUND ON PREP- THE AC IS SHORT CYCLING- CAUSE: States ac is short cycling. I don't think it's functioning incorrectly. I feel because it's such a small coach it gets to temperature very quickly.		W	1021 FORES
6	CORRECTION: NPF .10 HOURS COMPLAINT: FOUND ON PREP- TRIM TAPE ON WALL IN CABINET BELOW BOTTOM BUNK IS PEELING- CAUSE: Mfg. Flaw. Seam tape not applied in cubby. WILL NEED .10 FOR REPAIR CORRECTION: Pushed down tape and straightened it out, it is now sticking ok.		W	1021 FORES

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
NTTS	840821034507	12V 24 MDP BATTERY		I-PDI	1	85.20	85.20
NTTS	146508	BATTERY BOX GROUP 24		I-PDI	1	8.84	8.84

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
NTTS	RV1F-1A	NEW STOCK PREP			I-PDI	0.00	70.00	0.00
NTTS	RV1F-1A	NEW STOCK PREP		JGK	I-PDI	0.00	70.00	0.00
NTTS	RV1F-1A	NEW STOCK PREP		JGK	I-PDI	0.95	70.00	66.50
NTTS	RV1F-1A	NEW STOCK PREP		JGK	I-PDI	0.79	70.00	55.30
NTTS	RV1F-1A	NEW STOCK PREP		RW	I-PDI	0.83	70.00	58.10
	1 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00
	2 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00
	3 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00
	4 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00
	5 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00
	6 WARR	MANUFACTURER WARRANTY	RW		W-1021	0.50	140.00	70.00

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	94.04	179.90	0.00	0.00	0.00	273.94
W	1021	0.00	420.00	0.00	0.00	0.00	420.00

Continued on page 3

Work Order : 11730

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	94.04	599.90	0.00	0.00	0.00	693.94

&k2S
&k0S