

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11735

Date In:	11 FEB 25	Author:	KOTT
Promised Date:	15 MAR 25	Stock No:	
:		Year:	2022
Customer Name:	17615 - MYERS, NIKI	Manufacturer:	GRAND DESIGN
Address:	6612 VISTA VALLEY	Brand:	REREFLECTION
:	WINDSOR, WI	Model:	337RLS
Postal/Zip:	53598	Miles/Hrs:	
Phone#(res):	6152071026	Exterior Color:	
Phone#(bus):		Unit Type:	FW-FIFTH WHEEL
Cell Phone:		License#:	
Email:	NIKIMYERS@GMAIL.COM	Tag#:	DB 3/6
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	573FR3725N9917696	:	

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT:	CUSTOMER HAS CLAIM WITH GRAND DESIGN- CUSTOMER STATES THAT THE ODS SLIDE OUT THE MAIN SLIDE OUT- THE VERTICAL ALUMINUM BEAMS ARE COMING LOOSE- THE DS SLIDE OUT IS ALSO DOING THE SAME THING BUT NOT AS BAD- NEEDS TO BE INSPECTED FOR POSSIBLE FRAME ISSUES- YOU CAN ONLY SEE IF FROM THE INSIDE- CMR STATES THAT THE FASCIA PEICE IS MISSING AND YOU CAN SEE THE BEAM WERE IT IS ATTACHED AT THE TOP BUT NOT AT THE BOTTOM- ***SEE PICTURES****	W	1020 GRAND
	CAUSE:	Interior facia on ds and ods are seperating from the slide wall on the rear of both slides. Recommend new replacement slide walls. Will have to hyper extend both slides to do the repair.requesting 16 hours per slide wall. Would have to remove window on ds slide. And detach entertainment cabinet on ods slide.		
	CORRECTION:	... REQUESTING 32 HOURS APPROVED 24 HOURS		
WARR	WARRANTY REPAIR 1 - QUICK DISCONNECT RECALL	961563	W	1020 GRAND
WARR	COMPLAINT:	WARRANTY REPAIR 2- THE SLIDE TIMING IS OFF AND WILL NEED TO BE ADJUSTED ON BOTH REAR SLIDES	W	1020 GRAND
	CAUSE:	THE TIMING FOR THE SLIDE IS OFF CAUSING		

Continued on page 2

Work Order : 11735

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                THE BELL OF THE SLIDES TO BE COMPRESSED
                                AGAINST THE FRAME. WE WILL NEED TO TAKE
                                THE UNIT TO A SUBLET TO WELD THE FRAME
                                WHERE THE BELL SITS AND THEN READJUST
                                THE BELLS ON BOTH REAR SLIDES
CORRECTION: REQUESTING 3 HOURS (1.5 HOURS PER SLIDE)

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
   1  WARR      MANUFACTURER WARRANTY      W-1020    0.00  115.00    0.00
   1  WARR      MANUFACTURER WARRANTY TD    W-1020    0.36  115.00   41.40
ARR01 Z992      MISC LABOUR CODE (WARR      W-1020    0.00  115.00    0.00

```

```

*****
Job #  Sublet Description  SUBLET  bill to  Vendor  Total
*****
ARR02  BDT                                W-1020  329-BDT INC    0.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
   1  SC        SERVICE CALL      W-1020    1.00    3.75    3.75
   1  SSE        SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W      1020      0.00    41.40    0.00    3.75    0.00    45.15

      Totals      0.00    41.40    0.00    3.75    0.00    45.15

```

&k2S
&k0S