

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11798B

Date In: 26 SEP 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11356
: Year: 2025
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN
Address: 11333 COUNTY RD 2 Brand: MOMENTUM MAV
: MIDDLEBURY, IN Model: 24MAV
Postal/Zip: 46540 Miles/Hrs: 0
Phone#(res): 888-825-2820 Exterior Color:
Phone#(bus): Unit Type: TTH-TT TOY HAULER
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TM3029S1222451 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - the filter cap on W 1020 GRAND
the suction side of the water pump is
cracked in half
CAUSE: The clear cover for the pump filter on
the suction side cracked and was leaking
water, i replaced the filter and housing
CORRECTION: Done REQUEST .3
WARR COMPLAINT: WARRANTY REPAIR 2 - the screws on the W 1020 GRAND
bottom of both reliners are backing
themselves out, both chairs are held on
with 2 screws
CAUSE: The screws on the bottom of both chairs
came loose and fell out at some point
and put in a drawer, i put locktight on
them and put them back in, one screw is
missing
CORRECTION: Done REQUEST .6
WARR COMPLAINT: WARRANTY REPAIR 3 - the farthest right W 1020 GRAND
cabinet above the table is cracked.
CAUSE: The cabinet on the right side of the
table is cracked and will need to be
replaced.
CORRECTION: REQUEST .5
WARR COMPLAINT: WARRANTY REPAIR 4 - the top drawer W 1020 GRAND
between the stove and the fridge had a
cut above the handle and a chip in the
top left corner.
CAUSE: The top drawer between the fridge and
```

Continued on page 2

Work Order : 11798B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                the stove has a 4 inch scratch in it as
                well as top left corner has a chipped
                corner, it will need to be replaced
WARR    CORRECTION: .REQUEST .6
        COMPLAINT: WARRANTY REPAIR 5 - the main door will    W    1020    GRAND
                not shut properly because the door lock
                catch is mouted upsidedown
        CAUSE:      I flipped the lock catch around and
                lowered it but the deadbolt will not go
                in, if i lower it any lower the holes
                will be exposed, we will need a new door
        CORRECTION: REQUEST 1.5
    
```

```

*****
Job # Part No      Description          PARTS      Bill to   Qty      Price      Total
*****
WARR0 752324009329 SHURFLO PUMP FILTER      W-1020     1      13.74      13.74
WARR0 146881        NOVAFLEX SEALANT BLACK  W-1020     1      14.42      14.42
WARR0 EST        561567 - DOOR ENTRANCE 2 W-1020     0       0.00       0.00
    
```

```

*****
Job# Lab Code  Description          LABOUR    Mech Bill to   Hrs      Rate      Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.43    140.00     60.20
ARR01 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.07    140.00      9.80
ARR02 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.50    140.00     70.00
ARR03 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.50    140.00     70.00
ARR03 RV32A-2  CABINET DOOR R&R RVDA      W-1020     0.00    140.00      0.00
ARR04 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.50    140.00     70.00
ARR04 RV32A-11 DRAWER BOX REPAIR RVDA      W-1020     0.00    140.00      0.00
ARR05 Z992    MISC LABOUR CODE (WARR EG  W-1020     0.50    140.00     70.00
ARR05 O130    ENTRY DOOR ASSEMBLY, R      W-1020     0.00    140.00      0.00
    
```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      28.16      350.00      0.00      0.00      0.00      378.16
        Totals      28.16      350.00      0.00      0.00      0.00      378.16
    
```

&k2S
&k0S