

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11824

Date In: 25 MAR 25 Author: MGRAY  
Promised Date: 12 MAY 25 Stock No: 10708  
: Year: 2023  
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER  
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF SUPER-LITE T  
: CHICAGO, IL Model: 29RLBS  
Postal/Zip: 60673-1218 Miles/Hrs: 0  
Phone#(res): 219-534-3167 Exterior Color:  
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: TOD  
Purchased Date: 25 JUN 24 :  
Delivery Date: 02 JUL 24 :  
InService Date: :  
Serial#: 4X4TFLL24PZ185390 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 2 - Oven works but W 1021 FORES  
doesn't heat right. Will not get up to  
temperature of 425 and is very slow to  
heat at all.  
CAUSE: Test oven for operation of temp.  
REQUEST 1.0 LABOR  
CORRECTION: Turned oven on to max setting of 490.  
Got up to 475.  
WARR COMPLAINT: WARRANTY REPAIR 1 - Panel under the bed W 1021 FORES  
towards the front of the camper has  
warped and distorted pulling off of the  
aluminum frame.  
CAUSE: Done REQUEST .5  
CORRECTION: Done  
WARR COMPLAINT: WARRANTY REPAIR 3 - Carpet next to the W 1021 FORES  
bed towards the bathroom is not attached  
and is loose.  
CAUSE: Carpet next to bed is loose and needs to  
be refastened. REQUEST .75  
CORRECTION: Had to unmount bed frame from slide  
floor, then tuck the carpet back under  
bed frame. Staple carpet down, then  
reattached bed frame.  
WARR COMPLAINT: WARRANTY REPAIR 4 - Carpet by fireplace W 1021 FORES  
will not lay down on the floor with  
slide out extended.  
CAUSE: Carpet near fireplace bunches up when  
slide is all the way out. REQUEST .5

Continued on page 2

Work Order : 11824

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: Adjusted stopping point of slideout at
the accuator to prevent carpet from
bunching up.
WARR   COMPLAINT: WARRANTY REPAIR 5 - Outdoor light on the W   1021   FORES
drivers side by the water hook up does
not work.
CAUSE:   Outside light by city water is burnt
out. REQUEST .25
CORRECTION: Installed new light. Tested good.
WARR   COMPLAINT: WARRANTY REPAIR 6 - Front awning has           W   1021   FORES
slits in it where the LED lights are
along the length of the awning. Should
be replaced.
CAUSE:   Check awning fabric for defects. Has
holes in it near the bead seam. Need to
order new fabric only with light. Awning
is 11'. request 2.5
CORRECTION: ...
WARR   COMPLAINT: WARRANTY REPAIR 7 - Rear A/C seems as if W   1021   FORES
not cooling as it should . Front A/C
works great. REAR A/C DOES NOT SEEM TO
BE COLD
CAUSE:   Check main ac for operation. REQUEST .5
CORRECTION: Intake temp 75 degrees. Discharge temp
50 degrees. With in normal parameters.
WARR   COMPLAINT: WARRANTY REPAIR 8 - Sealant on roof           W   1021   FORES
joints is cracking in places including
the slide outs. CMR CLEANED UP SOME TO
MAKE SURE THERE WASN'T DAMAGES FROM RAIN
WHEN DRIVING HOME.
CAUSE:   Roof inspection. Recommend a roof
reseal. REQUEST 3HRS
CORRECTION: ...
WARR   COMPLAINT: WARRANTY REPAIR 9 - Fireplace has a           W   1021   FORES
yellow sticker inside it that needs to
be removed.
CAUSE:   Remove stiker from fireplace. REQUEST
.25
CORRECTION: Stiker taken out.
WARR   COMPLAINT: WARRANTY REPAIR 10 - Bathroom vanity          W   1021   FORES
countertop front edge is cracked at the
center.
CAUSE:   25.5" wide x23 3/8" deep. Vanity counter
has a Crack in the front. Need to order
new one.
CORRECTION: ....
WARR   COMPLAINT: WARRANTY REPAIR 11 - Gray water tank          W   1021   FORES
indicator does not read empty when no
water is in the tank. NOW STARTED

```

Continued on page 3

Work Order : 11824

WORKING AFTER DRIVING.  
 CAUSE: Grey tank reads 1/3 when tank is empty.  
 CORRECTION: Recommend tank probe cleaner if continues.

WARR COMPLAINT: WARRANTY REPAIR 12 - Blind on entry door W 1021 FORES  
 window is warped at the top and keeps pulling out of the top retaining clips I have reinstalled it 3 times, should be replaced. BLIND IS BOWED AT THE TOP.  
 CAUSE: Blind in entrance door is warped on top. Need to order new one. 11.5 wide x 21.5 high.  
 CORRECTION: Installed new window shade.

WARR COMPLAINT: WARRANTY REPAIR 13 - Replace wall panels W 1021 FORES  
 on driver and passenger side rear slide outs that have wrinkled wall covering. - verify that is this not the same at the panel replace from 10702B  
 CAUSE: Paneling is peeling above dinette slide.  
 CORRECTION: Was able to heat shrink paneling .

WARR COMPLAINT: WARRANTY REPAIR 14 - KITCHEN SLIDE IS W 1021 FORES  
 STARTING TO SQUEAL GOING IN AND OUT. DID LUBE THE SLIDE BUT STILL CONTNUING TO MAKE NOISE.  
 CAUSE: Test slide out on kitchen. Making a squeeling noise.  
 CORRECTION: Lubricated slideout rams. Seams to help the noise.

WARR COMPLAINT: WARRANTY REPAIR 15 - BED PANEL ON THE W 1021 FORES  
 FRONT MOST SIDE HAS COME LOOSE FROM STRUCTURE. LOOKS BOWED IN TOWARD FRONT OF BED. WOULD LIKE TACTED BACK IN PLACE.  
 CAUSE: Fasten lower side panel under bed.  
 CORRECTION: Refstened panel under bed that had popped loose.

\*\*\*\*\*

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WARR0	822020341	LIGHT PORCH LED OVAL W/S	W-1021	W-1021	1	5.77	5.77
WARR1	848150059901	LIPPERT THIN SHADE KIT	W-1021	W-1021	1	116.01	116.01

\*\*\*\*\*

\*\*\*\*\*

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR02	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.50	140.00	70.00
ARR01	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.50	140.00	70.00
ARR03	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.25	140.00	35.00
ARR04	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.50	140.00	70.00
ARR05	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.50	140.00	70.00
ARR06	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.00	140.00	0.00
ARR07	Z992	MISC LABOUR CODE	(WARR TD	W-1021	W-1021	0.50	140.00	70.00

\*\*\*\*\*

Continued on page 4

Work Order : 11824

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR08 Z992      MISC LABOUR CODE (WARR TD W-1021  0.00  140.00  0.00
ARR09 Z992      MISC LABOUR CODE (WARR TD W-1021  0.50  140.00  70.00
ARR10 Z992      MISC LABOUR CODE (WARR TD W-1021  0.00  140.00  0.00
ARR11 Z992      MISC LABOUR CODE (WARR TD W-1021  0.50  140.00  70.00
ARR12 Z992      MISC LABOUR CODE (WARR TD W-1021  0.36  140.00  50.40
ARR13 Z992      MISC LABOUR CODE (WARR TD W-1021  0.00  140.00  0.00
ARR14 Z992      MISC LABOUR CODE (WARR TD W-1021  0.12  140.00  16.80
ARR15 Z992      MISC LABOUR CODE (WARR TD W-1021  0.21  140.00  29.40
ARR03 Z992      MISC LABOUR CODE (WARR TD W-1021  0.25  140.00  35.00
ARR15 Z992      MISC LABOUR CODE (WARR TD W-1021  0.29  140.00  40.60
ARR10 Z992      MISC LABOUR CODE (WARR TD W-1021  0.13  140.00  18.20
ARR12 Z992      MISC LABOUR CODE (WARR TD W-1021  0.14  140.00  19.60
ARR13 Z992      MISC LABOUR CODE (WARR TD W-1021  0.50  140.00  70.00
ARR14 Z992      MISC LABOUR CODE (WARR TD W-1021  0.38  140.00  53.20
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021  0.02  140.00  2.80
ARR08 Z992      MISC LABOUR CODE (WARR TD W-1021  0.36  140.00  50.40
ARR13 Z992      MISC LABOUR CODE (WARR TD W-1021  0.00  140.00  0.00
ARR10 RV32A-7    COUNTERTOP R&R (PER RU W-1021  0.00  140.00  0.00
*****

```

BILLINGS SUMMARY

```

Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1021        121.78  911.40  0.00  0.00  0.00  1,033.18
Totals       121.78  911.40  0.00  0.00  0.00  1,033.18

```

&k2S  
&k0S