

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11840B

Date In: 02 FEB 26 Author: MGRAY
Promised Date: 31 DEC 26 Stock No: 11365
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: CEDAR CREEK EXPERIENCE
: WISCONSIN RAPIDS, WI Model: 35RL
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB: 2/2
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4FCRL23SS234489 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - Kitchen faucets push W 1021 FORES
button for spray mode is missing
CAUSE: 1019 MISSING PART
CORRECTION: Put in new faucet
WARR COMPLAINT: WARRANTY REPAIR 2 - Scratch on wood W 1021 FORES
valance above dining table
CAUSE: Scratch from mfg
CORRECTION: Used wood marker to cover request: .1
APPROVED: .1
WARR COMPLAINT: WARRANTY REPAIR 3 - mark on wall behind W 1021 FORES
the bench seat
CAUSE: Stain on wall looked like blood once I
began wiping it away
CORRECTION: Used some murpheys oil soap to scrub
away the mark on wall REQUEST: .1
APPROVED: .1
WARR COMPLAINT: WARRANTY REPAIR 4 - floor coverings in W 1021 FORES
living room have stains in a few areas
CAUSE: Stains in floor coverings from mfg
CORRECTION: I used cleaner and cloth to remove
stained areas on fabric floor coverings
REQUEST: .3 APPROVED: .5
WARR COMPLAINT: WARRANTY REPAIR 5 - bottom edge of bed W 1021 FORES
the finish is peeling up
CAUSE: Peeled edge
CORRECTION: Used a razor to carefully remove the
lifter bottom edge then used wood pen to
go over bottom edge of bedframe FORGOT

Continued on page 2

Work Order : 11840B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                TO PUNCH OUT ONLY TOOK 6 MIN PKEASE
                                ADJUST MY TIME THANK YOU  REQUEST: .2
                                APPROVED: .1
WARR    COMPLAINT:  WARRANTY REPAIR 6 - wall panel in           W    1021  FORES
                                bathroom popped loose near top
                                CAUSE:  Wall panel popped away from stud
                                CORRECTION: I was able to resecure with the pin
                                nailer with longer pin nails  REQUEST:
                                .1 APPROVED: .2
    
```

```

*****
Job # Part No Description           PARTS           Bill to  Qty  Price  Total
*****
WARR0 82200670 SINK, KITCHEN, PART, FAUCET  W-1021      1    62.43  62.43
    
```

```

*****
Job#  Lab Code  Description           LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50  140.00  70.00
ARR01 W150      FAUCET, R & R           JL      W-1021      0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49  140.00  68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01  140.00   1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.10  140.00  14.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.25  140.00  35.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.05  140.00   7.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.00  140.00   0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.20  140.00  28.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49  140.00  68.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01  140.00   1.40
    
```

```

*****
Job #  Excode  Description           EXTRAS  bill to  Qty  Price  Total
*****
ARR01  FRT      FREIGHT FOR WARR01 FAUCET  W-1021      1.00  19.48  19.48
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id           Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021              62.43  364.00   0.00   19.48   0.00  445.91
                                Totals      62.43  364.00   0.00   19.48   0.00  445.91
    
```

&k2S
&k0S