

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11840B

Date In:	02 FEB 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11365
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	CEDAR CREEK EXPERIENCE
:	CHICAGO, IL	Model:	35RL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 2/2
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4FCRL23SS234489	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - Kitchen faucets push W	1021	FORES
	CAUSE:	button for spray mode is missing Missing rubber cover on faucet sprayer head Please order rubber cover for faucet head or new faucet		
	CORRECTION:	 request: .6 (I can not find just replacement button, requesting full faucet replacement.)		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Scratch on wood W	1021	FORES
	CAUSE:	valance above dining table Scratch from mfg		
	CORRECTION:	Used wood marker to cover request: .1		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - mark on wall behind W	1021	FORES
	CAUSE:	the bench seat Stain on wall looked like blood once I began wiping it away		
	CORRECTION:	Used some murpheys oil soap to scrub away the mark on wall REQUEST: .1		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - floor coverings in W	1021	FORES
	CAUSE:	living room have stains in a few areas Stains in floor coverings from mfg		
	CORRECTION:	I used cleaner and cloth to remove stained areas on fabric floor coverings REQUEST: .3		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - bottom edge of bed W	1021	FORES
	CAUSE:	the finish is peeling up Peeled edge		
	CORRECTION:	Used a razor to carefully remove the		

Continued on page 2

Work Order : 11840B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
                    lifter bottom edge then used wood pen to
                    go over bottom edge of bedframe FORGOT
                    TO PUNCH OUT ONLY TOOK 6 MIN PKEASE
                    ADJUST MY TIME THANK YOU REQUEST: .2
WARR      COMPLAINT:  WARRANTY REPAIR 6 - wall panel in          W      1021      FORES
                    bathroom popped loose near top
CAUSE:      Wall panel popped away from stud
CORRECTION: I was able to resecure with the pin
                    nailer with longer pin nails REQUEST:
                    .1

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50  140.00  70.00
ARR01 W150      FAUCET, R & R          W-1021      0.00  140.00   0.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49  140.00  68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01  140.00   1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.10  140.00  14.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.25  140.00  35.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.05  140.00   7.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.00  140.00   0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.20  140.00  28.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49  140.00  68.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01  140.00   1.40

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021          0.00      294.00          0.00          0.00          0.00      294.00

Totals          0.00      294.00          0.00          0.00          0.00      294.00

```

&k2S
&k0S