

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2568706
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4FCRL23SS234489
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	020 / 020
Labor rate:	\$140.00	ITEM #	CRF35RL
OWNER INFORMATION		DEALER RO #	11840B
		CLAIM START DATE	02/02/2026
		CLAIM END DATE	03/11/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code 60-139-01-00-001543	Operational Description Single Handle Kitchen Faucet with Pullout Sprayer - Plumbing/Kitchen (Galley) Sink/Replace/No Tread Code	
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:19:52 :: Complaint: Kitchen faucets push button for spray mode is missing. Cause; Missing rubber cover on faucet sprayer head. Correction: Replace faucet as we cannot find a part for just the rubber cover.		
Model#	Dlr Sub Hrs	0.60	Sub Labor Amt \$84.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$70.00
	Notes AUTHORIZED		

Line# 1	Item #		Description			
	F100650670		SINK, KITCHEN, PART, FAUCET ONLY, STAINLESS STEEL, FOR 27"			
			RAINFALL SINK [DA7] V#RVF-SS SS			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$62.43	Sub Freight	\$19.48
	Appr Qty	1.00	Appr Dlr Price	\$62.43	Appr Freight	\$19.48
	Notes					

Line# 2	Operation Code		Operational Description	
	30-99-24-00-001030		Valance - Interior/Soft Goods/Repair/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:21:12 :: Complaint: Scratch on wood valance above dining table. Cause: Scratch from manufacturer. Correction: Used wood marker to cover.			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$14.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00	
Notes				

Line# 1	Item #	Description				
	USERPART	shop supplies - wood marker				
	Model #	Serial #			Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.70	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.70	Appr Freight	\$0.00
	Notes					

Labor

Line# 3	Operation Code		Operational Description	
	24-30-102-002279		Wall Panel - Repair/Interior/Panels, Ceilings, & Interior Moldings	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:22:02 :: Complaint: Mark on the wall behind the bench seat. Cause: Stain on wall, looked like blood once I began wiping it away. Correction: Used some murpheys oil sop to scrub away mark on wall.			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$14.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00	
Notes				
AUTHORIZED				

Part

Line# 1	Item #		Description		
	USERPART		shop supplies - murphys oil soap		
Model #		Serial #		Part tag	
Sub Qty		1.00	Sub Dlr Price	\$0.70	Sub Freight \$0.00
Appr Qty		1.00	Appr Dlr Price	\$0.70	Appr Freight \$0.00
Notes					

Labor

Line# 4	Operation Code		Operational Description	
	30-103-04-00-001119		Carpet - Interior/Flooring/Clean/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:22:59 :: Complaint: Floor coverings in living room have stains in a few areas. Cause: Stains in floor coverings from manufacturer. Correction: Used cleaner and cloth to remove stained areas on fabric floor coverings.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$70.00	
Notes				
AUTHORIZED				

Part

Line# 1	Item #		Description		
	USERPART		shop supplies - cleaner		
Model #		Serial #		Part tag	
Sub Qty		1.00	Sub Dlr Price	\$3.50	Sub Freight \$0.00
Appr Qty		1.00	Appr Dlr Price	\$3.50	Appr Freight \$0.00
Notes					

Labor

Line# 5	Operation Code		Operational Description	
	24-30-98-000996		Bed Structure - Repair/Interior/Beds, Mattress	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:24:10 :: Complaint: Bottom edge of bed, the finish is peeling up. Cause: Peeled edge. Correction: Used razor to carefully remove the lifted bottom edge then used wood pen to go over bottom edge of bed frame.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00	
Notes				
PHOTO IS BLURRY, PLEASE PROVIDE CLEAR PHOTO OF ISSUE				
Hello, yes, the photo is blurry, but you can still see where the bed was peeling up and needed to be repairs. Unfortunately, that is the only photo the tech provided, and they already did the repair. We can upload a photo of the completed repair if you would like to see the difference. Thanks.				
AUTHORIZED, PLEASE NOTE PHOTOS MUST BE CLEAR WHEN SUBMITTING.				

Part

Line# 1	Item #		Description		
	USERPART		shop supplies - wood pen		

Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$0.70	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.70	Appr Freight	\$0.00

Notes

Labor

Line# 6	Operation Code	Operational Description
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction	
	Original Note : greeneway@dealer-advisors.com, 2026-02-02 19:26:00 :: Complaint: Wall panel in bathroom popped loose near the top. Cause: Wall panel popped away from stud. Correction: Resecure with the pin nailer with longer pin nails.	

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$28.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$28.00

Notes

Part

Line# 1	Item #	Description
	USERPART	shop supplies - nails
	Model #	Serial #
	Sub Qty	1.00
	Appr Qty	1.00
	Sub Dlr Price	\$1.40
	Appr Dlr Price	\$1.40
	Part tag	
	Sub Freight	\$0.00
	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$238.00	Approved	Labor Amt	\$210.00
	Parts & Freight	\$88.91		Parts & Freight	\$88.91
	Total	\$326.91		Total	\$298.91

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	