

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11862B

Date In: 27 AUG 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11330
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA CAMPING EDITION
: WISCONSIN RAPIDS, WI Model: 305BHCE
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 9/4
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 5ZT2PUWBXS4023994 :

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. ODS SLIDE DECAL W 1021 FORES
LOOKS LIKE IT IS BUBBLING AND DECAL ON
DS DOES TOO 2. SILICONE THROUGHOUT
EXTERIOR 3.SILICONE GLOBS THROUGHOUT
EXTERIOR 4.BEDROOM DOOR HAS PAINT
CHIPPING 5.BUNKROOM BUNK CORNERS NEED
TO BE SMOOTHED OUT
CAUSE: Several decals on both sides are
bubbleing and will need to be replaced,
the bunk beds had some fraying wood on
the corners i cut away the stuff
sticking up and puttyed it, the main
bedroom door closest to the front door
was hanging loose because the screws
pulled out of the door, i moved the
bracket slightly and adjuster it.
CORRECTION: Done.
WARR COMPLAINT: WARRANTY REPAIR 1 -The tank fill probes W 1021 FORES
are not grounded to the frame and will
not read.
CAUSE: Tank probes werent reading, they we not
grounded properly. I added a ground wire
to the frame.
CORRECTION: Done. REQUEST: .75 HOURS OF LABOR
1 COMPLAINT: Several decals on both sides are W 1021 FORES
bubbleing
CAUSE: CAME FROM MFG THIS WAY- UNSURE AS TO WHY
THEY ARE BUBBLING attempted to heat the

Continued on page 2

Work Order : 11862B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                decals to lay flat to no avail. also
                tried to poke small pin holes in the
                decal to lay flat. did not work. will
                need to be replaced. there are 14
                decals in total
CORRECTION: will need to be replaced- request 7
                hours of labor (.50 hours per decal)
2 COMPLAINT: the bunk beds had some fraying wood on W 1021 FORES
                the corners i cut away the stuff
                sticking up and puttyed it
CAUSE: FROM MFG- UNSURE AS TO WHY IT WAS
                FRAYING
CORRECTION: i cut away the stuff sticking up and
                puttyed it REQUEST .30 HOURS OF LABOR
3 COMPLAINT: the main bedroom door closest to the W 1021 FORES
                front door was hanging loose
CAUSE: the screws pulled out of the door
CORRECTION: i moved the bracket slightly and
                adjuster it. REQUEST .30 HOURS OF LABOR
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
DAF Z991 DAF-WARRANTY REPAIR EG W-1021 0.10 140.00 14.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.35 140.00 49.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.15 140.00 21.00
2 WARR MANUFACTURER WARRANTY EG W-1021 0.30 140.00 42.00
3 WARR MANUFACTURER WARRANTY EG W-1021 0.30 140.00 42.00
    
```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
    
```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 0.00 168.00 0.00 0.00 0.00 168.00
Totals 0.00 168.00 0.00 0.00 0.00 168.00
    
```

&k2S
&k0S