

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2282422  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4FFLN22S1908672  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010C  
 ITEM # FLFF374DBH  
 DEALER RO # 11878B  
 CLAIM START DATE 04/30/2025  
 CLAIM END DATE 06/11/2025

Labor rate: \$140.00

**OWNER INFORMATION**

JOHN A TRENT  
 W9480 COUNTY RD S  
 New London, WI 54961  
 USA

Retail Date of Purchase 05/01/2025

WARRANTY EXPIRATION DATE

05/01/2026

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 20-78-01-00-004533      Awning Head/Motor Cover - Exterior/Awnings (Lippert)/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-04-30 12:43:21 :: Complaint: Missing the cover on awning arm, rear most awning the back arm. Cause: Missing awning arm cover. Correction: Obtained a cover from parts, it's off of an extra awning arm so no part number attached. Additional Note : greeneway@dealer-advisors.com, 2025-04-30 12:46:31 :: Unsure on labor code for this. Additional Note : greeneway@dealer-advisors.com, 2025-04-30 12:57:46 :: Part pulled from the parts department doesn't fit- dealership needs to order part.

Model# 1	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial# 1	Appr Hrs	0.30	Appr Labor Amt	\$42.00

**Notes**

**Part**

Line# 1      **Item #**      **Description**  
 F100233031      AWNING PART - 3M-1: FRONT DRIVE HEAD COVER FOR REGAL AWNING ARMS - BLACK - V# 643922

Model #	Serial #	Part tag	
Sub Qty 1.00	Sub Dlr Price \$7.20	Sub Freight	\$18.41
Appr Qty 1.00	Appr Dlr Price \$7.20	Appr Freight	\$18.41

**Notes**

**Labor**

Line# 2      **Operation Code**      **Operational Description**  
 30-99-24-00-001011      Curtains - Interior/Soft Goods/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-04-30 12:47:21 :: Complaint: The curtain bracket in the bedroom DS is not attached to the wall. Cause: Improperly installed. Correction: Installed 2 screws to curtain bracket and installed curtain.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$14.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$14.00

**Notes**

**Labor**

Line# 3      **Operation Code**      **Operational Description**  
 40-112-24-11-001350      Monitor Panel Wiring or Harness - Electrical/Monitor Panel/Repair/Electrical  
**Complaint, Cause, Correction**

