



Warranty Claim Form

Date: 11/20/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3820S9929636
Reflection 324MBS
Retail Purchase Date: null
Work Started: 10/23/2025
Work Completed: 10/23/2025

Claim Status: Paid
Dealer Work Order #: 11897B
Unit Offline Date: 3/31/2025

Claim #: 946387
Labor: \$98.00
Parts: \$19.90
Shipping: \$2.88
Total: \$123.08

Notes: TG 10-31-25 170049 photo's required

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: The main door trim on the left side came apart from the wall.

Hours: .2

Cause: The trim around the door pulled off the wall.

Amount: 28.00

Remedy: Nailed it back on.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 420004 Lights (Exterior) - R&R Tail Light *Fault Code:* Improper Installation/Build

Problem: The right bottom taillight is cracked.

Hours: .2

Cause: The outer reflector on the bottom right tail light was cracked and about to snap off.

Amount: 28.00

Remedy: Put a new reflector on it.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
421278 LIGHT TAIL 6" RED LED OVAL W/REVERSE LIGHT	LIGHT TAIL 6" RED LED OVAL W/ REVERSE LIGHT		1	1	19.90

Operation Line # 3

Flat Rate Code: 170049 Slide Out Assembly - Slim Rack- Gear *Fault Code:* Improper Installation/Build Rack- R&R

Problem: The bunk room slide is out of alignment. One side comes in faster than the other.

Hours: .3

Cause: The slim-rack system was pushing one side out before the other.

Amount: 42.00

Remedy: Did a factory reset on it and put it back in sync. Unsure on labor code.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

Operation Line # 4

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified Fee

Problem: Invoice 1445097

Hours: 0

Cause: Invoice 1445097

Amount: 0.00

Remedy: Invoice 1445097

Sublet Repairs: \$2.30

Manufacturer #:

Model #:

Serial #: