



Warranty Claim Form

Date: 10/13/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2624S3443488
Imagine 22MLE
Retail Purchase Date: 8/19/2025
Work Started: 9/22/2025
Work Completed: 9/22/2025

Claim Status: Paid
Dealer Work Order #: 12096
Unit Offline Date: 4/29/2025

Claim #: 932422
Labor: \$98.00
Parts: \$86.42
Shipping: \$14.40
Total: \$208.79

Notes: RJ 08/06/25

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

STEVEN STORM
N2173 DUGINSKI RD
MERRILL, Wisconsin 54452
United States
7152187842

Operation Line # 1

Flat Rate Code: 710021 Ducting - R&R Floor or Ceiling Register/ *Fault Code:* Improper Installation/Build Vent

Problem: Screen on vent in kitchen is loose.

Hours: .2

Cause: Improper install at factory.

Amount: 28.00

Remedy: I thought the tens were broken, but after pushing, I found I was able to push each tab in and now the screen is good.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 550032 Sealing - Attachments

Fault Code: Improper Installation/Build

Problem: 7 Screw heads are popping up around vents on roof and 2 bubbles in dicor on the roof.

Hours: .2

Cause: From manufacturer.

Amount: 28.00

Remedy: Cleaned areas well then dicored over the screw heads and popped the bubbles.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) Fault Code: Improper Installation/Build

Problem: Trim above the loveseat has a rather large gap in it.

Hours: .1

Cause: From manufacturer.

Amount: 14.00

Remedy: Filled the gap with putty.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 4

Flat Rate Code: 680009 Bedding - R&R Bedspread

Fault Code: Damaged/Maintenance

Problem: Backside of bed covering which was sealed in a bag has stains, so it was put into the bag dirty.

Hours: .2

Cause: Manufacturer stains on back of bed covering, it was put into the sealed bag this way from factory.

Amount: 28.00

Remedy: Replace bed covering.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
684095 BEDSPREAD 80 X 90 RL HONEYCOMB WHITE	BEDSPREAD 80 X 90 RL HONEYCOMB WHITE		1	1	86.42

Operation Line # 5

Flat Rate Code: 950003 Misc. Charges - Handling Fee

Fault Code: No Problem Identified

Problem: Invoice 1468834

Hours: 0

Cause: Invoice 1468834

Amount: 0.00

Remedy: Invoice 1468834

Sublet Repairs: \$9.97

Manufacturer #:

Model #:

Serial #: