

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12205

Date In: 11 JUN 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11319
: Year: 2025
Customer Name: 17594 - TRENT, JOHN Manufacturer: FOREST RIVER
Address: W9480 COUNTY RD S Brand: FLAGSTAFF CLASSIC FW
: NEW LONDON, WI Model: 374DBH
Postal/Zip: 54961 Miles/Hrs: 0
Phone#(res): 920-716-0643 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JTRENT1@GMAIL.COM Tag#: PWA- 7/17
Purchased Date: 17 JAN 25 :
Delivery Date: 01 MAY 25 :
InService Date: :
Serial#: 4X4FFLN22S1908672 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: 6/10-CUSTOMER STATES THAT THE REFER IN W 1021 FORES
THE EXTERIOR KITCHEN IS BOLTED TO FAR
FORWARD- THE LATCH FOR THE COMPARTMENT
DOOR HITS THE DOOR OF THE REFER CAUSING
A DENT-
CAUSE: CONFIRMED CUSTOMERS CONCERN- WILL NEED
TO REBOLT THE REFER FARTHER BACK AND
REPLACE IT-
CORRECTION: REQUEST 1 HOUR OF LABOR
2 COMPLAINT: 6/10- CUSTOMER STATES THAT THERE IS A W 1021 FORES
BLEMISH ON THE COUNTER TOP BY THE ENTRY
DOOR- PER THE CUSTOMER IT SEEMS LIKE THE
FINISH IS MISSING ON SOME SPOTS OF THE
COUNTER TOP-
CAUSE: WILL NEED TO REPLACE THE COUNTER TOP
CORRECTION: REQUEST 2 HOURS OF LABOR
3 COMPLAINT: 6/10- CUSTOMER STATES THAT THE BLACK AND W 1021 FORES
GRAY TANK SENSORS ARE NOT WIRED
CORRECTLY- HE STATES THAT WHEN YOU FLUSH
THE GRAY TANK THE BLACK TANK SENSOR
READS AS FULL-
CORRECTION: WILL NEED TO DIAGNOSE- REQUESTING 1 HOUR
OF LABOR
4 COMPLAINT: 6/10- CUSTOMER STATES THAT THERE IS A W 1021 FORES
SECTION OF LINO IN THE BEDROOM THAT
"STICKS UP"/ DOES NOT SIT FLUSH WITH THE
FLOOR- IT IS ON THE ODS OF THE ROOM
UNDER THE WINDOW-

Continued on page 2

Work Order : 12205

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: REQUEST 1 HOUR OF LABOR TO LAY THE LINO
          BACK FLAT
5  COMPLAINT: 6/10- CUSTOMER STATES THAT WHEN YOU HAVE W    1021  FORES
          THE FRONT DS COMPARTMENT DOOR OPEN, YOU
          CAN SEE SUNLIGHT COMING THROUGH AROUND
          THE STEPS GOING UP INTO THE BEDROOM-
CORRECTION: WILL NEED TO LOOK INTO ONCE THE UNIT IS
          HERE FOR SERVICE
6  COMPLAINT: CUSTOMER STATES THAT THE STRUT ON THE          W    1021  FORES
          AWNING DOES NOT WORK PROPERLY-
CAUSE:    VERIFIED THE CUSTOMERS CONCERN
CORRECTION: WILL NEED TO REPLACE THE STRUT FOR THE
          AWNING- THE STRUT IS A 280343 REQUEST
          .75 HOURS OF LABOR
7  COMPLAINT: CUSTOMER STATES THAT ON THE WATER INLET W    1021  FORES
          ON THE BOTTOM OF THE UNDERBELLY THERE IS
          NO CAP ON IT TO SEAL IT OFF- BIRDS BUILT
          A NEST IN THE UNDERBELLY OF HIS UNIT-
CORRECTION: WILL NEED TO INSTALL A WATER INLET
          FINISHING CAP- REQEUST .50 HOURS OF
          LABOR
8  COMPLAINT: WHEN THE CUSTOMER GOT HOME ON THE DAY OF W    1021  FORES
          THE SHOWTHRU FOUND THAT THERE ARE SCUFFS
          ON THE AWNINGS-
CAUSE:    VERIFIED CUSTOMERS CONCERN-
CORRECTION: WILL NEED TO R&R THE AWNINGS- REQUEST 3
          HOURS OF LABO R

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 WARR MANUFACTURER WARRANTY W-1021 0.00 140.00 0.00
5 WARR MANUFACTURER WARRANTY W-1021 0.00 140.00 0.00
4 WARR MANUFACTURER WARRANTY W-1021 0.00 140.00 0.00
3 WARR MANUFACTURER WARRANTY W-1021 0.00 140.00 0.00
2 WARR MANUFACTURER WARRANTY W-1021 0.00 140.00 0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
Totals 0.00 0.00 0.00 0.00 0.00 0.00

```

&k2S
&k0S