

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12217

Date In: 14 JUN 25 Author: MGRAY
Promised Date: 31 DEC 25 Stock No: 11424
: Year: 2025
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: SOLITUDE
: WISCONSIN RAPIDS, WI Model: 310GK
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FS3621SAA21933 :

| Job # | Description | JOB INFORMATION | Type | Bill To |
|-------|---|-----------------|------|------------|
| CEN | CLEAN EXTERIOR- NEW | | I | PDI PRE-D |
| NFWS | COMPLAINT: NEW FIFTH WHEEL STOCK PREP | | I | PDI PRE-D |
| | CAUSE: New unit prep | | | |
| | CORRECTION: Complete prep done | | | |
| 1 | COMPLAINT: FOUND WHILE TRANSFERRING THE FURNITURE | | W | 1020 GRAND |
| | FOUND THAT THE CONVERTOR IS NOT PUTTING OUT ANY POWER- | | | |
| | CAUSE: Check converter for operation. Not getting 12 volts. | | | |
| | CORRECTION: Found that both fuses were blown . Installed 2 new fuses. Tested good. REQ .30 HOURS OF LABOR | | | |
| WARR | COMPLAINT: WARRANTY REPAIR 1 - the fresh waters | | W | 1020 GRAND |
| | pull valve will not close I try filling tank and water comes out and handle does not push in | | | |
| | CAUSE: Improper install the clamp that holds the valve stem in place is way off to the side | | | |
| | CORRECTION: Moved clamp over so the rod pushes in straight REQ .10 HOURS OF LABOR | | | |
| WARR | COMPLAINT: WARRANTY REPAIR 2 - dicor needed on d | | W | 1020 GRAND |
| | few spots on the roof | | | |
| | CAUSE: Mfg | | | |
| | CORRECTION: Cleaned then sealed REQEUST .50 HOURS OF LABOR | | | |
| WARR | COMPLAINT: WARRANTY REPAIR 3 -kitchen faucet all of W | | W | 1020 GRAND |
| | a sudden stops allowing water through | | | |

Continued on page 2

Work Order : 12217

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Broken piece inside the faucet head I
         removed the faucet head and looked for
         debris nothing but the plastic plunger
         seems to be sticking and not allowing
         water through it works for a bit then I
         hear d snap sound dnd water quits
         running through the head but comes out
         of hose the head is attached to so it is
         a faulty spray head PLEASE ORDER NEW
         Kitchen FAUCET HEAD
CORRECTION: ..... REQUEST .75 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
CEN CE      CLEAN EXTERIOR      I-PDI      0.00  70.00    0.00
NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      1.09  70.00   76.30
  1 WARR     MANUFACTURER WARRANTY TD W-1020    0.50 140.00   70.00
NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      1.51  70.00  105.70
ARR01 Z992   MISC LABOUR CODE (WARR HOD W-1020    0.50 140.00   70.00
ARR02 Z992   MISC LABOUR CODE (WARR HOD W-1020    0.50 140.00   70.00
ARR03 Z992   MISC LABOUR CODE (WARR HOD W-1020    0.50 140.00   70.00
NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.08  70.00    5.60
NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      1.70  70.00  119.00
NFWS RV1F-1A NEW STOCK PREP      HOD I-PDI      0.12  70.00    8.40
ARR02 Z992   MISC LABOUR CODE (WARR HOD W-1020    0.00 140.00    0.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01 SSE     SHOP SUPPLIES - EXTERNAL W-1020  1.00  0.00    0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I  PDI        0.00  315.00  0.00   0.00   0.00  315.00
W  1020       0.00  280.00  0.00   0.00   0.00  280.00
Totals       0.00  595.00  0.00   0.00   0.00  595.00

```

&k2S
&k0S