

Operation Line # 3*Flat Rate Code:* 590046 Roof Vents - Reseal*Fault Code:* Improper Installation/Build*Problem:* Dicor needed on a few spots on the roof.*Hours:* .5*Cause:* From manufacturer.*Amount:* 70.00*Remedy:* Cleaned then sealed.*Sublet Repairs:* \$0.00*Manufacturer #:**Model #:**Serial #:***Operation Line # 4***Flat Rate Code:* 350016 Faucets - R&R Kitchen Faucet*Fault Code:* Component Failure*Problem:* Kitchen faucet all of a sudden stops allowing water through.*Hours:* .75*Cause:* Broken piece inside the faucet head. Removed the faucet head and looked for debris but nothing. *A m o u n t :* The plastic plunger seems to be sticking and not allowing water through it, it works for a bit then I hear a 105.00 snap sound and water quits running through the head but comes out of the hose the head is attached to. Faulty spray head*Remedy:* Replace kitchen faucet head. *unsure on proper labor code for just the head.*Sublet Repairs:* \$0.00*Manufacturer #:**Model #:**Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
350578 FAUCET BLACK FOR 27" RAINFALL SINK	FAUCET BLACK FOR 27" RAINFALL SINK		1	1	87.75

Operation Line # 5*Flat Rate Code:* 950003 Misc. Charges - Handling Fee*Fault Code:* No Problem Identified*Problem:* invoice 1463258*Hours:* 0*Cause:* invoice 1463258*Amount:* 0.00*Remedy:* invoice 1463258*Sublet Repairs:* \$10.13*Manufacturer #:**Model #:**Serial #:*