

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12240

Date In:	18 JUN 25	Author:	DLUCAS
Promised Date:	27 JUN 25	Stock No:	11167
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	402LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	28 JUN 24	:	:
Delivery Date:	11 JUL 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS26RP102822	:	:

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
SC CUSTOMER REQUESTS A SERVICE CALL TO THEIR UNIT: E 16584 PETRI  
32335 CTY RD G WOULD LIKE FREE SERVICE CALL \*NEED  
FREE SERVICE CALL VOUCHER TO HONOR\* OXFORD, WI DID  
NOT SUPPLY VOUCHER AS OF YET..  
1 COMPLAINT: AWNING GOES OUT BUT WILL NOT COME BACK W 1021 FORES  
IN ALL THE WAY, COMES IN A BIT BUT STOPS  
AND CANT GET IT IN WOULD LIKE ADDRESSED  
CAUSE: pics taken of parts used I checked  
voltage at awning switch 13.52 and  
checked voltage at motor was 13.51 I  
diagnose motor awning motor weak it  
extend and retracted but just slow  
retracting this is a really long awning  
CORRECTION: replaced the awning motor and awning  
switch I tested awning it extend and  
retracted slowly due to how long awning  
is  
2 COMPLAINT: CUSTOMER STATES SHADE IN HALLWAY NOT W 1021 FORES  
GOING UP WOULD LIKE LOOKED AT  
CAUSE: Will need new shade when it rolls up it  
all goes to one side  
CORRECTION: Will need a new shade for hallway....  
3 COMPLAINT: CUSTOMER STATES WALLPAPER AROUND WINDOWS W 1021 FORES  
IN A FEW SPOTS, WOULD LIKE TO MAKE SURE  
ITS NATURAL AND NOT WATER DAMAGED  
CAUSE: wall paper wrinkles around window frame  
work I had removed framework from one  
window and shown customer it's not water

Continued on page 2

Work Order : 12240

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                damage I had enough seam tape to do one
                window will need more seam tape and
                about will need about 3 more hours to do
                5 more windows
CORRECTION: Will need approval to do 5 more window
                i figure 3 hours to cut out wrinkles
                around window and seam tape ....

```

```

*****
Job # Part No Description           PARTS           Bill to   Qty   Price   Total
*****
1     154328 REPLACEMENT AWNING MOTOR WITH W-1021           1     451.20  451.20

```

```

*****
Job# Lab Code Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
1 WARR      MANUFACTURER WARRANTY JS   W-1021   1.70  140.00  238.00
2 WARR      MANUFACTURER WARRANTY JS   W-1021   0.50  140.00   70.00
3 WARR      MANUFACTURER WARRANTY JS   W-1021   1.10  140.00  154.00

```

```

*****
Job # Excode Description           EXTRAS           bill to   Qty   Price   Total
*****
SC SSE      SHOP SUPPLIES - EXTERNAL E-16584   1.00   0.00   0.00
SC SC       SERVICE CALL           E-16584  33.00   3.75  123.75

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id           Parts   Labour   Sublet   Extras   Tax   Total
*****
E   16584                0.00    0.00    0.00   123.75   6.81   130.56
W   1021                451.20  462.00    0.00    0.00    0.00   913.20

Totals                451.20  462.00    0.00   123.75   6.81   1,043.76

```

&k2S  
&k0S