

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12247B

Date In: 20 JUN 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11443
: Year: 2026
Customer Name: 116234 - JOHNSON, JAME Manufacturer: GRAND DESIGN
Address: 2525 S MEADOWVIEW LANE Brand: REFLECTION 150 SERIES
: APPLETON, WI Model: 260RD
Postal/Zip: 54915 Miles/Hrs: 0
Phone#(res): 920-585-4083 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JLJOHN4@SBCGLOBAL.NET; Tag#: 7/10- PARTS INQUIRY: 1
Purchased Date: 11 JUN 25 :
Delivery Date: 28 JUL 25 :
InService Date: :
Serial#: 573FR3124T3353872 :

Job # Description JOB INFORMATION Type Bill To

7 COMPLAINT: WHEN UNIT WAS DROPPED OFF FOUND THAT THE W 1020 GRAND
LINO IN THE BEDROOM ON THE RIGHT SIDE OF
THE BED IF YOU ARE AT THE FOOT IS NOT
TUCKED UNDER THE TRIM PIECE
CAUSE: WILL NEED TO REMOVE THE BLACK TRIM
THING, TUCK THE LINO DOWN UNDER IT, THEN
REINSTALL. WILL ALSO NEED TO REMOVE THE
BATTEN PIECE A THE TOP OF THE LINO
PIECE, LAY THE LINO DOWN, THEN REINSTALL
THE LINO-
CORRECTION: REQUEST 2 HOURS OF LABOR APPROVED 1.5
HOURS OF LABOR Removed the trim and the
box covering end of lino lifted glued
edges of lino tolled out and then
reinstalled trim all of the way around
8 COMPLAINT: AT THE TIME OF DROP OFF FOUND THAT THERE W 1020 GRAND
IS A DENT IN THE PROPANE COMPARTMENT
DOOR-
CAUSE: DENT IN THE COMPARTMENT DOOR- WILL NEED
TO BE REPLACED
CORRECTION: R&R COMPARTMENT DOOR- APPROVED .50
HOURS OF LABOR COMPLETE INSTALLED NEW
COMPARTMENT DOOR- CHECKS OKAY
1 COMPLAINT: AT THE TIME OF THE DROP OFF FOUND THAT W 1020 GRAND
THE WEDGE ON THE KING PIN IS DAMAGED- IT
IS BENT- WILL NEED TO REPLACED
CAUSE: WILL NEED TO REPLACE THE WEDGE-
CORRECTION: REQUEST .20 HOURS OF LABOR COMPLETE

Continued on page 2

Work Order : 12247B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  Transferred to GRV*12247C on 06 AUG 25   W    1020   GRAND
          Estimate amount was 0.00 WARRANTY REPAIR
          1 - Roof has a few bubbles in dicor
          CAUSE:      Gaps in dicor
          CORRECTION: Cleaned 2 small bubbles and sealed with
          leftover dicor after popping the bubbles
          REQUEST .10 HOURS OF LABOR
*****
```

```
*****
Job # Part No Description           PARTS           Bill to Qty Price Total
*****
8      82200804 DOOR BAGGAGE DRLUG07 16 X 25 W-1020 1 79.13 79.13
1      82200293 FRAME PIN BOX WEDGE TURNING W-1020 1 108.54 108.54
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.00 140.00 0.00
7 Z992 MISC LABOUR CODE (WARR HOD W-1020 1.50 140.00 210.00
1 WARR MANUFACTURER WARRANTY CF W-1020 0.50 140.00 70.00
8 WARR MANUFACTURER WARRANTY TD W-1020 0.50 140.00 70.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 0.00 0.00 0.00
8 FRT FREIGHT FOR JOB 8 W-1020 1.00 43.12 43.12
1 FRT FREIGHT FOR JOB 1 W-1020 0.00 0.00 0.00
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1020 187.67 350.00 0.00 43.12 0.00 580.79
Totals 187.67 350.00 0.00 43.12 0.00 580.79
*****
```

&k2S
&k0S