

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12367

Date In: 15 JUL 25 Author: DLUCAS
Promised Date: 31 DEC 25 Stock No: 11093
: Year: 2023
Customer Name: 14593 - VANDER MOLEN, Manufacturer: FOREST RIVER
Address: 4416 S 80TH ST Brand: PUMA TT
: GREENFIELD, WI Model: 32BHFS
Postal/Zip: 53220 Miles/Hrs: 0
Phone#(res): 4142026525 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: MJVANDERMOLEN@GMAIL.CO Tag#:
Purchased Date: 08 JUL 24 :
Delivery Date: 22 JUL 24 :
InService Date: :
Serial#: 4X4TPUH21PP098036 :

Job # Description JOB INFORMATION Type Bill To

SC CUSTOMER REQUESTS SERVICE CALL TO 1005 LONGBOW COURT E 14593 VANDE
ROME
1 COMPLAINT: CUSTOMER REQUESTS TOILET GASKET BE W 1021 FORES
LOOKED A IS NOT HOLDING WATER
CAUSE: pics taken of toilet found the inner
ball seal wasn't quite seal properly
check and see if the a recall toilet
CORRECTION: remove inner ball seal from toilet
cleaned and re attached properly filled
the bowl and toilet is holding at this
time REQ .75 HOURS OF LABOR
2 COMPLAINT: CUSTOMER STATES KEYS GIVEN TO HIM DO NOT W 1021 FORES
WORK THE DEADBOLT WOULD LIKE ADDRESSED
CAUSE: pics taken of code for lock so you would
have to call them and match it up
CORRECTION: Will need to match numbers with lock yo
key CUSTOMER HAS G366 KEYS, HAVE 2 G388
KEYS PULLED AND TAGGED FOR CMR REQ .10
HOURS OF LABOR
3 COMPLAINT: CUSTOMER STATES LP SELECTOR SWITCH BROKE W 1021 FORES
OFF WOULD LIKE ADDRESSED
CAUSE: pics taken of broken lp regulator and
Parr used
CORRECTION: remove and installed the new lp
regulator I also used lp Teflon on
threads that are not flared secured lp
lines and tested for leaks regulator is
ok REQ .75 HOURS LABOR

Continued on page 2

Work Order : 12367

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
4      COMPLAINT:  CUSTOMER STATES SEAM TAPE TO LEFT OF TV W   1021   FORES
      MOUNT COMING FREE WOULD LIKE ADDRESSED
      CAUSE:      pics taken rear bedroom left side of tv
      the seam tape is peeling back due to not
      enough seam tape on one panel like
      surface wise totally missed the staples
      CORRECTION: Will need seam tape .... REQUEST .75
      HOURS OF LABOR
  
```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty  Price  Total
*****
2      153425  GLOBAL REPL. KEY #388      W-1021      2    2.20   4.40
3      822040017 LP REGULATOR 2 STAGE AUTO C W-1021      1    62.41  62.41
  
```

```

*****
Job#  Lab Code  Description           LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1  WARR      MANUFACTURER WARRANTY JS  W-1021      0.00  140.00  0.00
2  WARR      MANUFACTURER WARRANTY JS  W-1021      0.50  140.00  70.00
3  WARR      MANUFACTURER WARRANTY JS  W-1021      0.50  140.00  70.00
4  WARR      MANUFACTURER WARRANTY JS  W-1021      0.50  140.00  70.00
1  WARR      MANUFACTURER WARRANTY JS  W-1021      0.50  140.00  70.00
  
```

```

*****
Job #  Excode  Description           EXTRAS           bill to  Qty  Price  Total
*****
SC  SSE      SHOP SUPPLIES - EXTERNAL E-14593      1.00   0.00   0.00
SC  SC       SERVICE CALL           E-14593     15.00   3.75  56.25
  
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id           Parts  Labour  Sublet  Extras  Tax  Total
*****
E  14593           0.00   0.00   0.00   56.25   3.11   59.36
W  1021          66.81  280.00   0.00   0.00   0.00  346.81

      Totals          66.81  280.00   0.00   56.25   3.11  406.17
  
```

&k2S
&k0S