



Warranty Claim Form

Date: 8/20/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT201XT8839855
Transcend 151BH
Retail Purchase Date: null
Work Started: 7/26/2025
Work Completed: 7/26/2025

Claim Status: Paid
Dealer Work Order #: 12373
Unit Offline Date: 6/10/2025

Claim #: 920202
Labor: \$126.00
Parts: \$2.60
Shipping: \$0.00
Total: \$128.60

Notes: Sg 8/7/25 *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 560049 Lg. Comp./Pass Thru/Kitch./Ent. Ctr. - Adjust/ *Fault Code:* Improper Installation/Build
Repair Door (includes door and frame)

Problem: Water heater seam is not sealed.

Hours: .2

Cause: Missing silicone on water heater seam.

Amount: 28.00

Remedy: Cleaned and dried seam then used left over clear silicone from prior job to seal.
*unsure on labor code.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 630006 Panel - Touch Up (per ceiling panel) *Fault Code:* Improper Installation/Build

Problem: Black marks on ceiling trim.

Hours: .2

Cause: Manufacturer defect.

Amount: 28.00

Remedy: Used quick solve to remove the black marks.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 690006 Blinds - R&R Wand

Fault Code: Improper Installation/Build

Problem: Missing blind rod

Hours: .1

Cause: Missing blind wand from manufacturer.

Amount: 14.00

Remedy: Installed one from parts.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	2.60

Operation Line # 4

Flat Rate Code: 550032 Sealing - Attachments

Fault Code: Improper Installation/Build

Problem: Roof sealant has bubbles in it.

Hours: .4

Cause: Bubbles in dicor from manufacturer.

Amount: 56.00

Remedy: Popped the bubbles and then filled with dicor and covered over with dicor.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: