

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2379257
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TFLC20PZ185158
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010D
 ITEM # FLT27BHWS
 DEALER RO # 12434
 CLAIM START DATE 07/25/2025
 CLAIM END DATE 08/05/2025

Labor rate: \$140.00

OWNER INFORMATION

KEITH D BERG
 3810 Downing Street
 Wisconsin Rapids, WI 54494
 USA

Retail Date of Purchase 07/25/2024 WARRANTY EXPIRATION DATE 07/25/2025

Claim Line Details

Labor

| | | |
|---------|-------------------------------------|--|
| Line# 1 | Operation Code 10-9-15-00-000168 | Operational Description Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/ No Tread Code |
|---------|-------------------------------------|--|

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-07-25 10:31:20 :: Complaint: Customer states that there is a hole in the underbelly that needs to be patched- WO was written up on 7/22/25 before warranty expiration.
 Cause: Hole in underbelly near the rear of the unit. The bolt that was holding the underbelly up pulled through the fabric. Correction: Added extra screw and large washer to pull belly material up into place to close up hole.

| | | | | |
|---------|-------------|------|----------------|---------|
| Model# | Dlr Sub Hrs | 0.50 | Sub Labor Amt | \$70.00 |
| Serial# | Appr Hrs | 0.50 | Appr Labor Amt | \$70.00 |

Notes

Authorized to repair

| | | | | | |
|------------------|-----------------|---------|-----------------|-----------------|---------|
| Submitted | Labor Amt | \$70.00 | Approved | Labor Amt | \$70.00 |
| | Parts & Freight | \$0.00 | | Parts & Freight | \$0.00 |
| | Total | \$70.00 | | Total | \$70.00 |

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.