

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12510

Date In: 31 JUL 25 Author: DLUCAS
Promised Date: 25 DEC 25 Stock No: 10999
: Year: 2024
Customer Name: 17047 - JENSEN, DIANE Manufacturer: GRAND DESIGN
Address: 17689 W 58TH DR Brand: REFLECTION TT
: GOLDEN, CO Model: 297RSTS
Postal/Zip: 80403 Miles/Hrs: 0
Phone#(res): 303-847-7613 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: DIJENSEGLDN@MSN.COM Tag#: DB: 8/18
Purchased Date: 09 SEP 23 :
Delivery Date: 03 AUG 24 :
InService Date: :
Serial#: 573TR3425R3348199 :

Job #	Description	JOB INFORMATION	Type	Bill To
SC	CUSTOMER REQUESTS SERVICE CALL TO W 19294 COUNTY ROAD Z BINAMWOOD		E	17047 JENSE
1	COMPLAINT: CUSTOMER STATES LIVING ROOM AC UNIT IS SHORT CYCLING BEDROOM HASNT TURNED ON		W	1020 GRAND
	CAUSE: will need to talk with furrion to find out if there's a control board room sensor replacement for both ac's pics taken of both ac's the ac in living short cycle due to room sensor			
	CORRECTION: will need to figure out temp issue with furrion fot short cycling- INSTALL A LONGER ROOM SENSOR AS THE ROOM SENSOR IS CURRENTLY CUTTING THE AC TO EARLY BECUASE IT IS RIGHT NEXT TO THE VENT THAT IS DUMPING COLD AIR ONTO THE SENSE FALSLY TELLING THE AC THAT THE ROOM IS DOWN TO TEMP- REQUEST: 2.50 HOURS OF LABOR TO INSTALL A LONGER ROOM SENSOR INTO BOTH AIR CONDITIONERS.			
2	COMPLAINT: CUSTOMER STATES BEDROOM AC IS NOT FUNCTIONING AS IT SHOULD COOLS MORE THAN THE BEDROOM AC		W	1020 GRAND
	CAUSE: second ac in bedroom reading cold in bedroom and ac will not come on until your turn ac temp way down			
	CORRECTION: will need to figure out temp issue with furrion fot short cycling- INSTALL A LONGER ROOM SENSOR AS THE ROOM SENSOR IS			

Continued on page 2

Work Order : 12510

 Job # Description JOB INFORMATION Type Bill To

 CURRENTLY CUTTING THE AC TO EARLY
 BECUASE IT IS RIGHT NEXT TO THE VENT
 THAT IS DUMPING COLD AIR ONTO THE SENSE
 FALSLY TELLING THE AC THAT THE ROOM IS
 DOWN TO TEMP- REQUEST: 2.50 HOURS OF
 LABOR TO INSTALL A LONGER ROOM SENSOR
 INTO BOTH AIR CONDITIONERS.

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 DIAG DIAGNOSTICS JS W-1020 1.00 140.00 140.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 SC SSE SHOP SUPPLIES - EXTERNAL E-17047 1.00 0.00 0.00
 SC SC SERVICE CALL E-17047 72.00 3.75 270.00

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 E 17047 0.00 0.00 0.00 270.00 14.85 284.85
 W 1020 0.00 140.00 0.00 0.00 0.00 140.00
 Totals 0.00 140.00 0.00 270.00 14.85 424.85

&k2S
 &k0S