

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12561B

Date In:	20 AUG 25	Author:	KOTT
Promised Date:	31 DEC 25	Stock No:	11413
:	:	Year:	2026
Customer Name:	17698 - LINDSAY, MARK	Manufacturer:	GRAND DESIGN
Address:	114 W BAEHR ST	Brand:	MOMENTUM G-CLASS TT
:	CECIL, WI	Model:	21G
Postal/Zip:	54111	Miles/Hrs:	0
Phone#(res):	9206558119	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TTH-TT TOY HAULER
Cell Phone:	:	License#:	:
Email:	mclindsay96@gmail.com	Tag#:	DB: 8/20
Purchased Date:	07 MAY 25	:	:
Delivery Date:	11 SEP 25	:	:
InService Date:	:	:	:
Serial#:	573TM2722T1223250	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
4      COMPLAINT:  WARRANTY REPAIR 1 - customer order unit  W    1020    GRAND
           the sheet says the rear awning over the
           porch with screen railings is suppose to
           have electric awning there is a switch
           for the 2nd awning but awning does not
           have a motor or wires to it the switch
           has wires but no power to wires
CAUSE:    Mfg did not install correct awning on
           this unit suppose to be electric but
           it's a manual the switch is wired and
           the fuse box has fuse for 2nd awning but
           awning has no motor or wires it is a
           manual awning  Please get electric
           awning and wires will need to be run
           also
CORRECTION:  INSTALL PROPER AWNING THAT WAS ORDERED
           BY THE CUSTOMER- REQUEST 3 HOURS OF
           LABOR COMPLETE PN:810440 WARR AUTH:  2
           HOURS OF LABOR
1      COMPLAINT:  Transferred to GRV*12561C on 16 OCT 25  W    1020    GRAND
           Estimate amount was 0.00 WHEN TECHS WENT
           TO INSTALL THE NEW POWER AWNING ON THE
           REAR OF THE UNIT, FOUND THAT THERE IS
           NOT POWER SUPPLY WIRE RUN TO THE REAR OF
           THE UNIT-
CAUSE:    When checking the power supply to the
           awning switch, found that the switch
           only had 8 volts. So we will have to run
```

Continued on page 2

Work Order : 12561B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
a new wire from the converter to the
switch threw the underbelly. Will need
to run 18' we have all the material
here to do the job. Will need hours
labor.

```

CORRECTION: ... REQUEST 5 HOURS OF LABOR

```

*****
Job # Part No  Description      PARTS      Bill to  Qty  Price      Total
*****
4      822010440  AWNING 8' BLK CASSETTE 12V  W-1020      1  1,385.48  1,385.48

```

```

*****
Job#  Lab Code  Description      LABOUR  Mech Bill to  Hrs  Rate      Total
*****
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
1 WARR      MANUFACTURER WARRANTY  TD  W-1020      0.00  140.00      0.00
4 WARR      MANUFACTURER WARRANTY  TD  W-1020      2.00  140.00      280.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      1385.48      280.00      0.00      0.00      0.00      1,665.48

Totals      1385.48      280.00      0.00      0.00      0.00      1,665.48

```

&k2S
&k0S