



Warranty Claim Form

Date: 1/7/2026

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573FR2820S3353351

Reflection 22RK

Retail Purchase Date: 5/30/2025

Work Started: 12/15/2025

Work Completed: 12/5/2025

Claim Status: Paid

Dealer Work Order #: 12562

Unit Offline Date: 4/16/2025

Claim #: 954865

Labor: \$364.00

Parts: \$46.42

Shipping: \$14.44

Total: \$430.10

Notes: JH 8/19 810112 Not a factory defect. Denied. 710073 No problem found. Denied. GD only cover diag time if a manufacturing defect is found.

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$140.00

Customer Information

GREGORY BRONIEC
1142 W QUEENS WAY
NEKOOSA, Wisconsin 54457
United States
7154591101

Operation Line # 1

Flat Rate Code: 620026 Floor Covering - Repair Linoleum Main Floor(per *Fault Code:* Improper Installation/Build
ln. ft., including attachments)

Problem: Vinyl in the bedroom on the passenger side of the bed is loose.

Hours: 2

Cause: Linoleum is lifted up from under front overhang.

Amount: 280.00

Remedy: Trim off to resecure lino back down.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 350031 Showers - Repair Shower Stall (1 pc. *Fault Code:* Improper Installation/Build
fiberglass)

Problem: Shower surround is missing some anchors.

Hours: .2

Cause: Shower surround moves a lot on the faucet side.

Amount: 28.00

Remedy: Added 4 fasteners to surround.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		4	1	1.00

Operation Line # 3

Flat Rate Code: 420044 Outlets/Recepts - R&R Shoreline Cord *Fault Code:* Damaged/Maintenance
Recept

Problem: Door where the power cord plugs in is loose.

Hours: .4

Cause: Door won't stay latched.

Amount: 56.00

Remedy: Need to replace the whole 50 amp inlet.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag</u> <u>#</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
420776 RECEPT BLACK 50A INLET TWIST LOCK BLACK SQUARE	RECEPT BLACK 50A INLET TWIST LOCK BLACK SQUARE		1	1	45.42

Operation Line # 4

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified
Fee

Problem: Invoice 1467801

Hours: 0

Cause: Invoice 1467801

Amount: 0.00

Remedy: Invoice 1467801

Sublet Repairs: \$5.24

Manufacturer #:

Model #:

Serial #: