

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12625

Date In:	27 AUG 25	Author:	MGRAY
Promised Date:	04 SEP 25	Stock No:	11223
:	:	Year:	2025
Customer Name:	89167 - DOHNER, JAMES	Manufacturer:	GRAND DESIGN
Address:	E 10 861 TERRYTOWN ROA	Brand:	SOLITUDE
:	BARABOO, WI	Model:	310GK
Postal/Zip:	53913	Miles/Hrs:	0
Phone#(res):	608-356-3307	Exterior Color:	:
Phone#(bus):	608-393-5040	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	MR.JIMDOHNER@GMAIL.COM	Tag#:	sent text with update
Purchased Date:	14 AUG 24	:	:
Delivery Date:	23 SEP 24	:	:
InService Date:	:	:	:
Serial#:	573FS3627SAA19975	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -banging noise when      W    1020    GRAND
          putting slide in. need looked at for
          repair  **Additional notes**Please have
          camper level, then slide out #1 follow
          it by slide our#2. #2 will make a load
          bang before it starts the slide "In"
          process. We always slide in #1 first
          then #2. Slide 2 is the one that will
          bang at the start of slide in.
          CAUSE:      Check to see if slideouts bang when they
          go in and out.
          CORRECTION: banging is from the jam nut hitting the
          stopping plate  REQUEST .50 HOURS OF
          LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 2 - damaged shower door, W    1020    GRAND
          it is the door that is to the right when
          facing it. handle came off
          CAUSE:      Door handle for shower glass door fell
          off.
          CORRECTION: Reattached handle on door. REQUEST .45
          HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - there is loose trim W    1020    GRAND
          pieces that need to be refastened.
          CAUSE:      Loose trim on ceiling in bedroom and in
          kitchen floor next to slide out by
          refer.
          CORRECTION: Had to add more staples to ceiling panel
          in the bedroom in order to bring the
```

Continued on page 2

Work Order : 12625

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
seam more even so the trim would sit
flush. then refastened the trim in
kitchen. REQUEST .50 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 4 - lights on the awning W      1020    GRAND
the left side is hanging down from where
its supposed to be
CAUSE:      Check awnig lights for uneven track
insertion.
CORRECTION: Lughts look good. Nothing out of place.
REQUEST .50 HOURS OF LABOR
RI       COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF      I      PD      GOODW
REPAIR IS NEEDED.
CAUSE:      roof inspection.
CORRECTION: touched up a couple of vents with dicor.
They had a couple of air bubbles that
popped. All good now.

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR TD  W-1020  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR TD  W-1020  0.33  140.00  46.20
ARR04 Z992      MISC LABOUR CODE (WARR TD  W-1020  0.50  140.00  70.00
  RI Z991      PREFORM ROOF INSPECTIO TD  I-PD    0.30   70.00  21.00
ARR03 Z992      MISC LABOUR CODE (WARR TD  W-1020  0.17  140.00  23.80

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PD          0.00     21.00     0.00     0.00     0.00     21.00
W      1020        0.00    280.00     0.00     0.00    11.56    291.56

Totals          0.00    301.00     0.00     0.00    11.56    312.56

```

&k2S
&k0S