



Claim CLAIM42197 (C3885448)

Last Modified By

								Changed			
	Reference	Repair	Repair					Labor	warranty	Date of	
Claim	no.	start date	date	VIN	Pre-auth	Dealer	Repairing dealer name	rate	rate	Type	Purchase
CLAIM42197 (C3885448)	12831B	10/24/2025	10/24/2025	4YDTHPT2XS9330185	PA03924412	1612	Greeneway Inc 8220 State Hwy 13 S Wisconsin Rapids, WI 54494	140.00	0.00	WARR	1/1/1970

Deny	Item				Qty	Dealer	Part	Appr	Sub		
code	number	Name	Quantity	Returned	price	Markup	total	Freight	Freight	Sublet	Status
94	719736	Water Heater - Tankless "On Demand" - 60,000 BTU - ST-60	1	0	399.00	30.00	518.70	30.00	41.98	0.00	Approved

501 9/14/24-KRV does not pay expedited freight **Component Model 1** **Component Serial Number** Winterization crack

	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	2	0	0.73	30.00	1.90	0.00	0.00	0.00	Approved
--	--------	---	---	---	------	-------	------	------	------	------	----------

KRV-Approved for part only as goodwill (non-warranty)

90	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	2	0	0.73	30.00	1.90	0.00	0.00	0.00	Approved
----	--------	---	---	---	------	-------	------	------	------	------	----------

Component Serial Number kinked lines

	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	2	0	1.47	30.00	3.82	0.00	0.00	0.00	Approved
--	--------	---	---	---	------	-------	------	------	------	------	----------

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4131015B	Water Heater - Suburban - Replace - Complete	0	0	0	0	1	1.3	Denied
Complaint The copper lin on the left side of the water heater is leaking. Cause A copper line on the water heater is broken and leaking. Correction Replace water heater. KRV-Approved for part only as goodwill (non-warranty)									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6109314A	Holding Tank Flusher, Fill	0.5	0.5	70	0	1	0.2	Approved
Complaint Both black tank flush lines are kinked. Cause Both black tank flush lines by the water pump are kinked. Correction Cut the kink out and put in a 90 in. Time reflect TWO lines, not just one.									

Submitted parts & subLet				526.32	Approved parts & subLet	526.32
Submitted labor & subLet				70.00	Approved labor & subLet	70.00
Submitted freight				41.98	Approved freight	30.00
Total Submitted				<u>638.30</u>	Total approved	<u>626.32</u>