

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12888

Date In:	04 OCT 25	Author:	MGRAY
Promised Date:	25 DEC 25	Stock No:	10304
:	:	Year:	2022
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE
:	MIDDLEBURY, IN	Model:	2910BH
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 10/14
Purchased Date:	11 JUN 22	:	:
Delivery Date:	27 JUN 22	:	:
InService Date:	:	:	:
Serial#:	573TE3426N6639508	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
RI      COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF      I      PD      GOODW
        REPAIR IS NEEDED.
        CAUSE:      1001 CUSTOMER REQUESTED.  All the
                    sealant looks good but the connectors on
                    the end of the wiring for the solar
                    panel are broke.  We would have to
                    replace the wire connectors and the
                    solar connector thats mounted to the
                    roof.
        CORRECTION:  ...
2      COMPLAINT:  24v-861 - quick disconnect recall          W      1020      GRAND
        CAUSE:      Recall. I replaced the quick disconnect
                    and tested it. I had to scub it to try
                    to make out the engravings.
        CORRECTION:  Done. REQ .60 HOURS OF LABOR warr auth:
                    .60
3      COMPLAINT:  RECALL ON I-BEAM CRACKING - CHECK OUT      W      1020      GRAND
        FOR EST.
        CAUSE:      Recall. I inspected both sides and i
                    dont see and visible cracking.
        CORRECTION:  Done. REQ .50 HOURS warr auth: .20
1      COMPLAINT:  FOUND ON ROOF INSPECTION- THE SOLAR          E      16272      HOFFM
        CONNECTORS ARE CRACKED AND NEED TO BE
        REPLACED- ROUGHLY $175
        CAUSE:      Broken solar connector.  I cut the
                    wires and put new connectors on it. I
                    cut the sealant, removed the solar
                    plate, hooked the new plate up, secured
```

Continued on page 2

Work Order : 12888

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
it to the roof, and sealed around it.
While i was replacing the plate i
noticed the front ods screw track is
pulling away from the side wall and has
the potential to let water in. I pulled
the screw cover molding off and the
screws pulled through the track in
spots. I predrilled some holes and added
larger screws to suck it and sealed the
edge with silicone.
CORRECTION: Done.

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty    Price    Total
*****
3      822020061 QUICK DISCONNECT X 1/4 BRAS W-1020      1      24.01    24.01
1      822020945 SOLAR ROOF TOP ELECTRICAL B E-16272      1      46.49    46.49

```

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to   Hrs    Rate    Total
*****
RI Z991      PREFORM ROOF INSPECTIO JGK  I-PD      0.30    70.00    21.00
2 WARR      MANUFACTURER WARRANTY  JGK  W-1020    0.60    140.00    84.00
3 WARR      MANUFACTURER WARRANTY  JGK  W-1020    0.20    140.00    28.00
1 Z990      MISC LABOUR CODE (EXTE JGK  E-16272    0.29    130.00    37.70
1 Z990      MISC LABOUR CODE (EXTE JGK  E-16272    0.61    130.00    79.30

```

```

*****
Job #  Excode   Description      EXTRAS      bill to   Qty    Price    Total
*****
RI  SSE        SHOP SUPPLIES - EXTERNAL  I-PD      1.00     8.78     8.78

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E  16272          46.49      117.00        0.00        0.00        9.02      172.51
I  PD              0.00       21.00        0.00        8.78        0.00       29.78
W  1020          24.01      112.00        0.00        0.00        0.00     136.01

Totals          70.50     250.00        0.00        8.78        9.02     338.30

```

&k2S
&k0S