

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2547956
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUWB8T4026037
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$140.00	ITEM #	PUT305BHCE-1
OWNER INFORMATION		DEALER RO #	13054
		CLAIM START DATE	01/12/2026
		CLAIM END DATE	02/24/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor				
Line# 1	Operation Code	Operational Description		
	40-196-12-00-001306	LED Light - Electrical/12 Volt Interior/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-01-12 13:44:15 :: Complaint: Light above the main bed works intermittently. Cause: Loose wire. Correction: Removed the lens, dropped light down, secured wire into connector. Light no longer flickers. Additional Note : greeneway@dealer-advisors.com, 2026-01-12 13:45:37 :: No code for wire repair			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$14.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$14.00
	Notes			

Line# 2	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2026-01-12 13:46:38 :: Complaint: Drawer under kitchen sink does not latch. Cause: The catch was not installed far enough forward to catch good. Correction: Removed the drawer, loosened the screw on catch, moved forward, tightened the screws, reinstalled the drawer. Tested the drawer and it now catches as it should. Additional Note : greeneway@dealer-advisors.com, 2026-01-12 13:47:01 :: No repair code.		
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$42.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$14.00
Notes flat rate		

Line# 3	Operation Code		Operational Description	
	30-102-24-00-003061		Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-01-12 13:47:40 :: Complaint: Deep staple holes in ceiling trim of slide out. Cause: Deep holes in trim from manufacturer. Correction: Used putty to cover.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$14.00	
Notes				
flat rate				

Line# 1	Item #	Description	
	USERPART	Shop supplies - Putty	
	Model #	Serial #	Part tag

Sub Qty	1.00	Sub Dlr Price	\$0.70	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.70	Appr Freight	\$0.00

Notes

Labor

Line# 4

Operation Code
60-144-01-00-001649

Operational Description
Dometic Sealand Toilet Floor Flange Seal - Includes R&R Toilet - Plumbing/Toilet (Dometic, Sealand)/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-01-12 13:50:11 :: Complaint: Toilet is leaking at its base. Cause: Bad seal. Correction: Removed water line, removed toilet, removed seal, installed new seal and reinstalled toilet. Tested and no more leaks.

Model# 1 **Dlr Sub Hrs** 1.30 **Sub Labor Amt** \$182.00

Serial# 1 **Appr Hrs** 0.75 **Appr Labor Amt** \$105.00

Notes

flat rate
.50 repair
.25 additional diag per vendor (see repair code)

Part

Line# 1

Item #	Description				
USERPART	DOM385311652 Kit, MTG Hardware - WHT 300				
Model #	Serial #	Part tag			
Sub Qty 1.00	Sub Dlr Price \$32.54	Sub Freight	\$0.00		
Appr Qty 1.00	Appr Dlr Price \$32.54	Appr Freight	\$0.00		

Notes

Labor

Line# 5

Operation Code
20-43-01-00-000589

Operational Description
Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-02-05 11:18:19 :: Complaint: Front decal is peeling. Cause: Peeling decal at top DS line decal is peeled up. Correction: Replace decal.

Model# **Dlr Sub Hrs** 0.50 **Sub Labor Amt** \$70.00

Serial# **Appr Hrs** 0.50 **Appr Labor Amt** \$70.00

Notes

per request

Part

Line# 1

Item #	Description				
F100604150	GRAPHIC; #110 LARGE FR W/WINGS-BLK # FR-25-93625A (REPLACES FR-24-89944A W/FR IN WHITE LETTERING)				
Model #	Serial #	Part tag			
Sub Qty 1.00	Sub Dlr Price \$8.65	Sub Freight	\$19.43		
Appr Qty 1.00	Appr Dlr Price \$8.65	Appr Freight	\$19.43		

Notes

Labor

Line# 6

Operation Code
20-69-01-17-000700

Operational Description
Key Lock - Exterior/Compartment Doors/Replace/Latch

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-02-05 11:19:34 :: Complaint: Baggage lock is not catching. Cause: Manufacturer installed it incorrectly and it would not latch at all. Correction: Removed the lip off baggage lock, flipped around and it's too loose so I bent the lip gently out a bit and installed it how it originally was with the lip bent out a bit and it now locks and unlocks as it should.

Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$42.00

Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$14.00

Labor

Line# 7

Notes

flat rate

Operation Code

20-69-24-00-000699

Operational Description

Compartment Door Frame - Exterior/Compartment Doors/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2026-02-05 11:20:31 :: Complaint: Silicone smeared on exterior of the unit. Cause: Silicone smears from manufacturer. Correction: Used quick solve to remove the silicone.

Model#

Dlr Sub Hrs

0.20

Sub Labor Amt

\$28.00

Serial#

Appr Hrs

0.20

Appr Labor Amt

\$28.00

Notes

Part

Line# 1

Item #

USERPART

Description

shop supplies - quick solve cleaner

Model #

Serial #

Part tag

Sub Qty

1.00

Sub Dlr Price

\$1.40

Sub Freight

\$0.00

Appr Qty

1.00

Appr Dlr Price

\$1.40

Appr Freight

\$0.00

Notes

Submitted	Labor Amt	\$406.00	Approved	Labor Amt	\$259.00
	Parts & Freight	\$62.72		Parts & Freight	\$62.72
	Total	\$468.72		Total	\$321.72

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.