

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13163B

Date In:	30 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11565
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF E-PRO
:	CHICAGO, IL	Model:	17LE
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 1/30 - waiting on
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	5ZT2FSJCXT3040342	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Water pump does not W    1021    FORES
        come on
        CAUSE:      The connection on power to fuse to pump
                   both were not allowing power through
        CORRECTION: I removed panel to access pump removed 2
                   screws holding pump into place cut the
                   fuse wire out then restriped the two
                   power wires and connected turned switch
                   to pump on it now has power. I then
                   wired the 10 amp fuse between the 2
                   wires after restriping both ends of that
                   wire tested powers on once again then I
                   recrimped both and tested it is powering
                   on . I screwed the pump back down and
                   put panel back In to place REQUEST .5
                   APPROVED: .5
WARR    COMPLAINT:  WARRANTY REPAIR 2 - wall panel next to W    1021    FORES
        the refer has popped away from the stud
        CAUSE:      1000 DEFECT FROM MANUFACTURER. I cut
                   the baton stip to size, nailed it on and
                   covered the holes with putty.
        CORRECTION: Done.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - The fabric lp cover W    1021    FORES
        has many splits in it
        CAUSE:      1000 DEFECT FROM MANUFACTURER. I
                   replaced the l.p. cover.
        CORRECTION: Done.
```

Continued on page 2

Work Order : 13163B

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
WARR0 82207708 BATTEN STRIP WOODGRAIN - SED W-1021 1 2.83 2.83
WARR0 82200860 PANELING -PFL: LAUAN - SEDON W-1021 1 57.06 57.06
WARR0 82204243 LP TANK COVER VINYL - BLACK W-1021 1 17.59 17.59
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 140.00 70.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.00 140.00 0.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.00 140.00 0.00
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 140.00 1.40
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.49 140.00 68.60
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.32 140.00 44.80
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 140.00 70.00
ARR03 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 140.00 70.00
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.00 140.00 0.00
ARR02 WARR MANUFACTURER WARRANTY JGK W-1021 0.18 140.00 25.20
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
ARR02 FRT FREIGHT W-1021 1.00 59.80 59.80
ARR02 FRT FREIGHT W-1021 1.00 129.00 129.00
ARR03 FRT FREIGHT W-1021 1.00 19.56 19.56
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 77.48 350.00 0.00 208.36 0.00 635.84
Totals 77.48 350.00 0.00 208.36 0.00 635.84
*****
```

&k2S
&k0S