

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13178

Date In:	08 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11573
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF SUPER-LITE T
:	CHICAGO, IL	Model:	26SFK
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	NOW SOLD TO BRUHA
Purchased Date:	24 JAN 26	:	:
Delivery Date:	04 JUL 26	:	:
InService Date:	:	:	:
Serial#:	4X4TFLF27TZ200311	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
CEN	COMPLAINT: CLEAN EXTERIOR- NEW		I	PDI PRE-D
	CAUSE: This was washed for show but Eric did not get undercarriage			
	CORRECTION: I desalted the underside of the unit then used soap in a bottle and sprayed undercarriage and rinsed			
NTTS	COMPLAINT: NEW TRAVEL TRAILER STOCK PREP		I	PDI PRE-D
	CAUSE: New unit			
	CORRECTION: Completed			
WS	COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF		I	PDI PRE-D
	CONTAINED - TOWABLE			
	CAUSE: Prepped unit			
	CORRECTION: Winterize complete			
1	COMPLAINT: HALF OF THE AWNING LIGHTS ARE NOT OPERATING- PARTS TAGGED IN THE WARRANTY CAGE		W	1021 FORES
	CAUSE: damage awning lights			
	CORRECTION: remove the damage awning lights frome fabric slide on new light to fabric and wired i also tested lights are working			
WARR	COMPLAINT: WARRANTY REPAIR 1 - 5 Ceiling trim have		W	1021 FORES
	black scrapes marks on them			
	CAUSE: Mfg left black marks and scrapes on white plastic ceilingtrim			
	CORRECTION: I used quick solve and liquid scouring agent to remove the black marks from 5 ceiling trim pieces REQ: .50 HOURS			
	APPROVED: .3			

Continued on page 2

Work Order : 13178

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Next to the ceiling   W    1021   FORES
          trim in dining /living room the ceiling
          has a cut
          CAUSE:      Slight cut in ceiling panel next to the
                      plastic ceiling trim
          CORRECTION: First cleaned to be sure it was not just
                      a pencil mark it is not then I used a
                      bit of off white / light tan putty to
                      fill the slight cut no longer able to
                      see this in ceiling panel  REQ: .30
                      APPROVED: .3
WARR    COMPLAINT:  WARRANTY REPAIR 3 - The awning light     W    1021   FORES
          strip was hanging down on arrival was
          removed
          CAUSE:      Light was hanging off on arrival .
                      Please order new awning light strip
                      ,Pics of the awning tag and tag on the
                      insert strip where the light slides into
                      also attached Order new light strip tag
                      info has measurement of the needed
                      lights length
          CORRECTION: ..... REQ: .60 dDECLINED

```

```

*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE I-PDI          3      6.62     19.86
1       822039412    AWNING PART - VDS: LED L W-1021          1    302.34    302.34

```

```

*****
Job#  Lab Code    Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
CEN CE          CLEAN EXTERIOR          HOD I-PDI        0.65    70.00    45.50
CEN CE          CLEAN EXTERIOR          HOD I-PDI        0.00    70.00     0.00
NTTS RV1F-1A    NEW STOCK PREP          HOD I-PDI        1.25    70.00    87.50
NTTS RV1F-1A    NEW STOCK PREP          HOD I-PDI        0.00    70.00     0.00
NTTS RV1F-1A    NEW STOCK PREP          HOD I-PDI        1.42    70.00    99.40
NTTS RV1F-1A    NEW STOCK PREP          HOD I-PDI        1.83    70.00   128.10
WS W495         WINTERIZE RV (WATER SY HOD I-PDI        0.70    70.00    49.00
WS W495         WINTERIZE RV (WATER SY HOD I-PDI        0.00    70.00     0.00
1 WARR          MANUFACTURER WARRANTY JS   W-1021        0.50   140.00    70.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021        0.50   140.00    70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021        0.49   140.00    68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021        0.01   140.00     1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021        0.50   140.00    70.00

```

Continued on page 3

Work Order : 13178

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
   1  FRT      FREIGHT          W-1021     1.00   328.55   328.55
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1021     1.00    0.00    0.00
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I   PDI           19.86    409.50     0.00      0.00      0.00     429.36
W   1021          302.34    280.00     0.00     328.55      0.00     910.89

      Totals      322.20    689.50     0.00     328.55      0.00    1,340.25

```

&k2S

&k0S