

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 9516B

Date In: 18 APR 24 Author: MGRAY
Promised Date: 04 MAY 24 Stock No: 10999
: Year: 2024
Customer Name: 17047 - JENSEN, DIANE Manufacturer: GRAND DESIGN
Address: 17689 W 58TH DR Brand: REFLECTION TT
: GOLDEN, CO Model: 297RSTS
Postal/Zip: 80403 Miles/Hrs: 0
Phone#(res): 303-847-7613 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: DIJENSENGLDN@MSN.COM Tag#: pu@st 5/4 @ 9AM
Purchased Date: 09 SEP 23 :
Delivery Date: 04 MAY 24 :
InService Date: :
Serial#: 573TR3425R3348199 :

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF REPAIRS: 1.RUBBER FLANGE AROUND W 1020 GRAND
EXHAUST VENT DOES NOT SIT RIGHT/VENT IS
BENT 2.PUTTY SPOTS ALONG LIVING/KITCHEN
TRIM DS 3. ISLAND COUNTER TOP SEPARATED
TOWARDS REAR OF CAMPER 4. CABINET DOORS
OUT OF ALIGNMENT IN REAR WALL ABOVE TV
AND HUTCH 5. BATH CABINET DOOR HAS ROUGH
EDGE AT TOP 6. SOFA- PUTTY MARKS - RT
BASE, RT REAR, LT ARM REST, LOOSE STITCH
IN RT SIDE ARM REST 7. OTTOMEN CUSHION
HAS STAIN ON IT - POSSIBLY FROM CLEANING
PUTTY.
CAUSE: Daf
CORRECTION: If problem found on own warranty lines
WARR COMPLAINT: WARRANTY REPAIR 1 - the roof has dicor W 1020 GRAND
gaps
CAUSE: Mfg left gaps when dicoring (sealing)
the roof
CORRECTION: Cleaned areas that had gaps I then
sealed with a tube of leftover dicor
from another job.
WARR COMPLAINT: WARRANTY REPAIR 2 -the water heater is W 1020 GRAND
throwing a error code
CAUSE: E5 code keeps coming up Removed vacuum
breaker and hose connected to it blew
out the hose a few times in between
testing code is still coming up NEED TO
ORDER NEW FURRIION WATER HEATER PICS

Continued on page 2

Work Order : 9516B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                TAKEN OF THE MODEL
CORRECTION: .
WARR    COMPLAINT:  WARRANTY REPAIR 3 - ods window next to   W    1020   GRAND
                dining table the window seal is popping
                out at each end it is bowed outwards
CAUSE:   Came from mfg this way improper install
CORRECTION: Pressed back into place
WARR    COMPLAINT:  WARRANTY REPAIR 4 -island countertop is  W    1020   GRAND
                separated towards rear of unit
CAUSE:   Separated bottom wood from counter top
                not glued well enough from mfg
CORRECTION: I pryed the bottom wood and top
                countertop apart enough to spray
                adhesive in the gap then clamped and
                let adhesive set up.
    
```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty    Price    Total
*****
WARR0 822040048 WATER HEATER TANKLESS 2.4 G W-1020      0    493.03    0.00
    
```

```

*****
Job# Lab Code  Description           LABOUR    Mech Bill to    Hrs    Rate    Total
*****
  DAF Z991    DAF-WARRANTY REPAIR    HOD  W-1020    0.10  115.00    11.50
ARR01 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.50  115.00    57.50
ARR01 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.00  115.00    0.00
ARR02 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.50  115.00    57.50
ARR03 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.49  115.00    56.35
ARR03 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.01  115.00    1.15
ARR04 Z992    MISC LABOUR CODE (WARR HOD  W-1020    0.50  115.00    57.50
    
```

```

*****
                BILLINGS SUMMARY
Type Bill Id    Parts    Labour    Sublet    Extras    Tax    Total
*****
W    1020    0.00    241.50    0.00    0.00    0.00    241.50
                Totals    0.00    241.50    0.00    0.00    0.00    241.50
    
```

&k2S
&k0S