



Warranty Claim Form

Date: 5/16/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2821P3432338

Imagine 23BHE

Retail Purchase Date: 4/27/2024

Work Started: 5/3/2025

Work Completed: 5/3/2025

Claim Status: Paid

Dealer Work Order #: 9935B

Unit Offline Date: 9/26/2022

Claim #: 894848

Labor: \$230.00

Parts: \$20.63

Shipping: \$19.75

Total: \$270.38

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

SHANE DORNFIELD
419 TIMBER HEIGHTS DRIVE
RHINELANDER, Wisconsin 54501
United States
715-630-6465

Operation Line # 1

Flat Rate Code: 310019 Termination (Gate) Valves - R&R Sewer *Fault Code:* Improper Installation/Build
Hose Holder

Problem: Broken sewer cap. Unsure on labor code for this one, please advise if incorrect.

Hours: .5

Cause: Sewer cap was broken.

Amount: 57.50

Remedy: Replaced sewer cap.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	0.00
310111 FITTING 3" BAYONET CAP WITH 8" STRAP	FITTING 3" BAYONET CAP WITH 8" STRAP		1	1	2.61

Operation Line # 2

Flat Rate Code: 590061 Decals - (Front & Rear Wall/Cap) - R&R Rear *Fault Code:* Improper Installation/Build
Decal/Logo/Die Cut

Problem: Front cap white decals peeling/damaged.

Hours: 1

Cause: Decals are starting to peel.

Amount: 115.00

Remedy: Replace decal.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
530175 DIE CUT FRONT # 6 LH IMAGINE	DIE CUT FRONT # 6 LH IMAGINE		1	1	7.53
530176 DIE CUT FRONT # 6 RH IMAGINE	DIE CUT FRONT # 6 RH IMAGINE		1	1	7.53

Operation Line # 3

Flat Rate Code: 660020 Sliding Doors (wood/glass) - Repair *Fault Code:* Improper Installation/Build Track

Problem: Barn door guide is missing.

Hours: .5

Cause: Barn door guide is missing, not on door.

Amount: 57.50

Remedy: Replace door guide.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
662659 BRACKET BARN DOOR GUIDE 16GA PC BLACK	BRACKET BARN DOOR GUIDE 16GA PC BLACK		1	1	2.96