

Operation Line 2

Flat Rate Code: 920005 Sealing - Attic Vent and Solar Dock *Fault Code:* TSB
Cracking

Serial #:

Model #:

Notes:

Problem: Attic vents and solar ports on affected units may prematurely crack allowing for water infiltration.

Time Requested: .3

Time Allowed: .3

Cause: Attic vents and solar ports on affected units may prematurely crack allowing for water infiltration.

Sublet Repairs: 0.00

Remedy: The corrective action is to inspect the roof for damage to the attic vent, and/or solar port. If components are cracked they should be replaced with parts supplied by GDRV.

Status: Approved

Operation Line 3

Flat Rate Code: 540004 Decking - R&R Roof Panels (per *Fault Code:* Damaged/Maintenance sheet)

Serial #:

Model #:

Notes:

Problem: Roof decking water damaged

Time Requested: 1

Cause: Cracks in roof attachments

Time Allowed: 1

Remedy: Replace affected decking sheets

Sublet Repairs: 0.00

Status: Approved with Modifications