

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2528674
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2ALTB4S9010709
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	501 / 501
OWNER INFORMATION		ITEM #	ALT2800KBH
BRITNEY KAYREN RINEHART		DEALER RO #	72604
220 LOS MIRADORES PL NE		CLAIM START DATE	12/16/2025
Rio Rancho, NM 87124		CLAIM END DATE	12/26/2025
USA			
Retail Date of Purchase	09/03/2025	WARRANTY EXPIRATION DATE	09/03/2026

Claim Line Details

Labor

Line# 1

Operation Code	30-102-24-00-001117	Operational Description
		Trim Molding, each - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 10:38:06 :: Complaint: Customer states when standing at foot of the bed, to the left you can see light coming in from the floor/wall. Cause: Light comes in through a gap in the storage compartment. Correction: Ran a bead of white silicone to seal gap in the compartment.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes
 Dealer has requested more time than what is normally approved for this repair.

Part

Line# 1

Item #	USERPART	Description			
		Silicone			
Model #		Serial #			
Sub Qty	1.00	Sub Dlr Price	\$1.40	Part tag	
Appr Qty	1.00	Appr Dlr Price	\$1.40	Sub Freight	\$0.00
				Appr Freight	\$0.00

Notes

Labor

Line# 2

Operation Code	30-102-12-00-001096	Operational Description
		Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 10:47:34 :: Complaint: Customer states panel on inside slide is coming loose. Cause: Slide trim is loose. Correction: Restapled slide trim.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes

Labor

Line# 3

Operation Code	SB-400-03-00-004604	Operational Description
		51-1834 – CARGO MOUNTED SLIDE & AWNING SWITCHES - PERFORM REMEDY - Technical Service Bulletin/Electronic Components/Install/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 10:49:53 :: Complaint: Active recall 001143 Cause:

Cargo mounted slide and awning switches Correction: Replace receptacle cover per recall

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$38.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

Part

Line# 1	Item #		Description			
	F100651112		RECEPT COVER, EXTERIOR BLK W/4 BLK WOOD SCREWS TSBKIT17961			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$7.15	Sub Freight	\$15.85
	Appr Qty	1.00	Appr Dlr Price	\$7.15	Appr Freight	\$15.85

Notes

Submitted	Labor Amt	\$114.00
	Parts & Freight	\$24.40
	Total	\$138.40

Approved	Labor Amt	\$95.00
	Parts & Freight	\$24.40
	Total	\$119.40

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.